

# Customer Management Report (Ventura) Redlight Incidents

Operator Id: %

01-Jul-2015 to 31-Jul-2015

Category	VE-BRJ0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents	15	253	10	19	163	44	23	83	84	9	34	54	24	46	42	12	45	29	989

## Less Uncontrollable Factors

Obstruction	1	21	1	0	3	0	2	2	2	0	1	1	2	1	13	0	2	2	54
Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	4	0	1	1	0	0	0	0	0	0	6
Motor Cycle Helmet	0	2	0	0	2	1	0	2	0	1	0	2	0	0	0	0	0	0	10
Plate Obstruction	1	10	1	0	7	1	1	0	0	1	1	2	0	0	1	0	0	1	27
Vehicle Obstruction	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	3
Driver Obstruction (PD)	0	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	3
Police Rejects	0	0	0	0	1	0	0	1	0	0	0	0	0	0	0	0	0	1	3
Incorrect/Incomplete DMV	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Invalid Offense	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Multiple vehicles in frame	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
On or Passed the Stop Bar (PD)	0	0	0	1	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
Plate Obstruction (PT)	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	2
Plate Underillible	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3
Safe Turn On Red	0	45	0	0	0	0	0	14	9	0	0	0	0	0	0	0	0	2	70
Sun Glare	0	11	0	0	2	2	0	0	0	0	0	1	1	1	0	0	1	0	19
Policy/Weather	1	3	0	1	2	0	0	0	1	0	0	0	0	0	0	0	0	0	9
Extended Vehicle	2	29	0	1	12	13	8	3	16	2	1	12	8	16	2	2	14	5	146
Sun Glare	0	6	0	0	7	0	0	1	6	0	0	0	0	3	0	0	0	1	24
Weather/Nature	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Registration Issues	0	3	0	5	5	3	2	1	3	0	2	0	0	0	0	0	0	0	1
Out of Country Plate	0	4	0	0	1	1	0	2	1	0	1	1	0	0	4	1	1	1	30
Paper Plates	0	139	2	8	45	21	14	28	42	4	7	21	11	22	22	3	21	15	18
Wrong or No DMV	5	4	0	0	1	1	0	2	1	0	1	1	0	0	0	0	0	0	430
Total	10	114	8	11	118	23	9	55	42	5	27	33	13	24	20	9	24	14	559
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	10	114	8	11	118	23	9	55	42	5	27	33	13	24	20	9	24	14	559

## Less Rejects

Camera Malfunction	0-00%	0-00%	1-12%	1-09%	0-00%	0-00%	1-11%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Face Not in Frame	0-00%	0-00%	0-00%	1-09%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	10-99%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	2-05%	0-00%	0-00%	2-05%	0-00%	1-04%	0-00%	0-00%	1-07%	1-00%	
Police Rejects	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Underillible Images poor	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Undercar	0-00%	1-10%	0-00%	2-18%	2-22%	2-05%	2-22%	2-05%	2-05%	0-00%	0-00%	2-05%	0-00%	1-04%	0-00%	0-00%	1-04%	0-00%	1-00%
Unclear Scene Image	2-20%	8-80%	7-88%	9-82%	117-99%	23-100%	7-78%	55-100%	40-95%	5-100%	27-100%	31-94%	13-100%	23-98%	19-95%	9-100%	24-100%	12-88%	531-95%
Approved Violations	8-80%	103-90%	7-88%	9-82%	117-99%	23-100%	7-78%	55-100%	40-95%	5-100%	27-100%	31-94%	13-100%	23-98%	19-95%	9-100%	24-100%	12-88%	531-95%
Total Notices Printed	8-80%	103-90%	7-88%	9-82%	117-99%	23-100%	7-78%	55-100%	40-95%	5-100%	27-100%	31-94%	13-100%	23-98%	19-95%	9-100%	24-100%	12-88%	531-95%
Generated By:	TRANNDALL																		
Generated On:	3/21/2016 12:33:14 PM																		

**Customer Management Report (Ventura) Redlight Incidents**  
 01-Jul-2015 to 31-Jul-2015 Operator id: %

VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MAT0-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	------------	-------

Legend: (P) = Production (I) = Inoperative  
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) Redlight Incidents

01-Aug-2015 to 31-Aug-2015 Operator Id: %

Category	VE-BRJ0-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents	17	241	2	17	174	48	45	93	76	17	68	63	35	59	85	24	79	30	1173

## Less Uncontrollable Factors

Obstruction	0	19	1	0	8	0	1	3	0	0	0	1	3	0	0	0	0	2	21	0	0	4	63
Driver Obstruction/Duckers	0	0	0	1	1	0	0	1	2	0	1	0	0	0	0	0	0	0	0	0	0	0	7
Motor Cycle Helmet	0	1	0	0	4	2	1	0	0	1	0	3	0	0	0	0	0	0	0	0	0	1	16
Plate Obstruction	3	16	0	1	6	0	6	1	0	0	2	3	0	1	3	1	1	1	3	1	1	0	41
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Police Rejects	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Chation Issued manually	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2	1	0	1	6
Driver Obstruction (PD)	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Emergency Vehicle Responding	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Incorrect/Incomplete DMV	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	0	0	0	4
Invalid Offense	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Multiple vehicles in frame	0	5	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	6
On or Passed the Stop Bar (PD)	0	4	0	0	4	1	0	3	1	2	5	0	1	0	1	0	1	0	1	1	3	6	32
Plate Obstruction (PD)	0	0	0	0	2	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	3
Plate Underntiable	0	3	0	0	2	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	6
Safe Turn On Red	0	46	0	0	0	0	0	15	6	2	0	0	0	0	0	0	2	0	0	0	2	3	74
Sun Turn On Red	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1	0	0	1	1	4
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Policy/Weath Extended Vehicle er	0	3	0	0	1	2	0	1	0	0	2	7	0	0	0	0	0	0	0	0	0	0	17
Sun Glare	2	28	0	0	16	13	22	3	28	3	5	9	9	30	1	5	16	4	1	1	16	194	
Weather/Nature	0	1	0	0	2	0	0	0	2	0	0	0	0	1	0	0	0	0	0	0	0	0	7
Registration Issues	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Can Not Identify State	1	3	0	0	8	2	2	7	1	0	1	0	0	3	0	0	0	0	0	0	0	0	36
Paper Plates	0	5	0	1	1	0	0	2	1	2	2	2	1	1	0	0	1	1	0	0	2	0	20
Wrong or No DMV	7	135	1	5	58	21	32	36	41	10	19	28	15	39	32	11	32	18	540	540	18	540	7
Total	10	106	1	12	116	27	13	57	35	7	49	35	20	20	53	13	47	12	633	633	12	633	7
Sub Total Violations	10	106	1	12	116	27	13	57	35	7	49	35	20	20	53	13	47	12	633	633	12	633	7
Less In Process	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	10	106	1	12	116	27	13	57	35	7	49	35	20	20	53	13	47	12	633	633	12	633	7

## Less Rejects

Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-23%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	0-00%	13-12%	0-00%	1-08%	3-03%	2-07%	1-08%	1-02%	1-03%	0-00%	0-00%	3-09%	1-05%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	27-04%
Incorrect Speed	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%

Generated By: TRANDALL  
Generated On: 3/21/2016 12:31:31 PM

# Customer Management Report (Ventura) Redlight Incidents

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total	1-10%	14-13%	0-00%	1-08%	4-03%	2-07%	5-38%	2-04%	2-06%	0-00%	0-00%	3-09%	1-05%	0-00%	5-09%	0-00%	1-02%	0-00%	41-08%
Approved Violations	9-90%	92-97%	1-100%	11-92%	112-97%	25-93%	8-62%	55-96%	33-94%	7-100%	49-100%	32-91%	19-95%	20-100%	48-91%	13-100%	46-98%	12-100%	592-94%
Total Notices Printed	9-90%	92-97%	1-100%	11-92%	112-97%	25-93%	8-62%	55-96%	33-94%	7-100%	49-100%	32-91%	19-95%	20-100%	48-91%	13-100%	46-98%	12-100%	592-94%

Legend: (P) = Production (I) = Inoperative  
 Note: If you selected "All" from the "Approach," drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) Redlight Incidents

01-Sep-2015 to 30-Sep-2015

Operator Id: %

Operator Id	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
23	213	5	17	162	51	32	114	101	16	56	70	24	45	94	33	64	38	1158	

## Total Processed Incidents

### Less Uncontrollable Factors

Obstruction	Driver Obstruction/Duckers	2	19	0	0	4	4	0	0	3	2	0	0	0	0	0	0	0	64
	Motor Cycle Helmet	1	0	0	1	2	0	0	1	5	0	0	0	0	0	0	0	0	13
	Plate Obstruction	1	0	0	0	6	2	0	1	0	1	0	0	0	0	0	0	0	14
	Vehicle Obstruction	1	9	0	1	11	2	2	1	1	3	0	2	8	0	2	0	47	
Police Rejects	Driver Obstruction (PD)	0	5	1	0	2	0	0	1	0	1	0	0	0	3	0	1	14	
	Incorrect/Incomplete DMV	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	4	
	Invalid Offense	0	0	0	2	2	1	0	1	3	4	0	0	0	0	6	0	25	
	Multiple vehicles in frame	1	12	0	0	2	1	0	1	0	0	0	0	2	0	0	0	22	
	On or Passed the Stop Bar (PD)	0	3	0	0	1	0	0	0	1	1	0	0	0	3	0	0	21	
	Plate Obstruction (PD)	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Plate Undeniable	1	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	6	
	Safe Turn On Red	0	38	0	0	0	0	0	0	0	0	0	0	0	0	0	0	82	
	Sun Glare	0	3	0	1	4	1	0	0	0	1	0	0	0	0	1	0	11	
	Policy/Weath	0	1	0	0	2	1	0	0	0	1	0	0	0	0	1	0	9	
	Extended Vehicle	0	28	0	1	24	9	15	12	2	8	13	7	26	8	2	12	180	
	Sun Glare	0	2	0	0	1	0	0	1	0	0	0	0	0	0	0	0	5	
	Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Registration Issues	Paper Plates	2	9	0	0	5	0	1	2	1	0	0	1	0	0	0	1	24	
	Wrong or No DMV	0	133	0	1	7	1	2	2	1	2	1	1	0	1	0	0	18	
Total		9	9	1	7	72	21	20	50	34	25	38	14	30	43	13	22	580	
Less In Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution		14	80	4	10	90	30	12	64	67	31	10	10	15	51	20	42	588	
		0	0	4	10	90	30	12	64	67	31	10	10	15	51	20	42	598	

### Less Rejects

Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
	Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	1-08%	1-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Rear Plate No Flash	1-07%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects	Driver Undeniable Images poor	0-00%	1-01%	0-00%	0-00%	0-00%	1-03%	1-08%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-01%
	No Images	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Plate Undicar	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total		1-07%	1-01%	0-00%	0-00%	1-01%	5-17%	3-25%	1-02%	1-01%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	19-03%	
Approved Violations		13-93%	79-99%	4-100%	10-100%	89-99%	25-93%	9-75%	63-98%	66-98%	10-100%	29-94%	31-97%	10-100%	14-93%	51-100%	19-95%	41-98%	16-100%
		13-93%	79-99%	4-100%	10-100%	89-99%	25-93%	9-75%	63-98%	66-98%	10-100%	29-94%	31-97%	10-100%	14-93%	51-100%	19-95%	41-98%	16-100%

Generated By: TRANDALL  
Generated On: 3/21/2016 12:28:26 PM

© Redflex Traffic Systems, Inc.

**Customer Management Report (Ventura) Redlight Incidents**  
**01-Sep-2015 to 30-Sep-2015** Operator Id: %

Total Notices Printed	13.93%	79.99%	4.100%	10.100%	89.99%	25.83%	9.75%	63.98%	66.99%	10.100%	29.94%	31.97%	10.100%	14.93%	51.100%	19.95%	41.98%	18.100%	579.97%
	VE-BRJC-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MAL E-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL

Legend: (P) = Production (I) = Inoperative  
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) Redlight Incidents

Operator Id: %

01-Oct-2015 to 31-Oct-2015

Category	VE-BRJO-01	VE-CATH-01	VE-FOV1-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	26	244	4	29	151	49	28	114	105	16	55	67	31	56	92	51	60	33	1211
<b>Less Uncontrollable Factors</b>																			
Obstruction	2	21	1	3	4	4	3	2	2	1	1	4	3	1	17	2	0	2	73
Driver Obstruction/Duckers	0	0	0	1	1	0	0	5	1	0	0	0	0	1	0	0	0	0	10
Motor Cycle Helmet	1	1	2	1	2	1	0	0	1	0	1	5	0	1	0	0	0	0	17
Plate Obstruction	1	12	0	0	6	0	1	0	1	0	1	3	1	0	6	1	0	1	34
Vehicle Obstruction	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
Police Rejects	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Driver Obstruction (PD)	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Incorrect Plate on Vehicle	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Invalid Offense	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	2
Multiple vehicles in frame	0	9	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	10
On or Passed the Stop Bar (PD)	3	12	0	4	2	1	0	10	1	2	5	0	1	1	1	7	13	3	66
Plate Obstruction (PD)	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Plate Undentifiable	1	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	3
Safe Turn On Red	0	11	0	0	0	0	0	9	0	0	0	0	1	0	0	0	0	0	30
Sun Glare	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	2
Extended Vehicle	0	2	0	0	0	0	0	0	0	0	1	5	1	0	0	1	0	0	10
Weather/Nature	2	33	0	3	12	5	0	17	0	0	4	9	6	21	8	2	4	3	129
Sun Glare	0	2	0	0	2	1	0	2	1	0	1	1	0	0	2	0	0	0	11
Registration Issues	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Out of Country Plate	3	9	0	2	1	3	1	4	4	0	2	3	1	2	2	0	0	0	45
Paper Plates	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Whrong or No DMV	15	116	3	14	35	15	7	36	1	5	17	32	16	27	38	19	21	19	471
<b>Total</b>	11	128	1	15	116	34	21	78	69	11	38	35	15	29	54	32	39	14	740
Sub Total Violations	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Less In Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	11	128	1	15	116	34	21	78	69	11	38	35	15	29	54	32	39	14	740
<b>Less Rejects</b>																			
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Police Rejects	0-00%	4-03%	0-00%	0-00%	1-01%	0-00%	0-00%	2-03%	2-03%	0-00%	1-03%	1-03%	0-00%	4-14%	3-06%	0-00%	0-00%	0-00%	21-00%
Driver Undentifiable Images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

# Customer Management Report (Ventura) Redlight Incidents

Operator Id: %

	VE-BRQ0-01	VE-CATH-01	VE-FOV-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Plate Unclear	1-09%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	2-06%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	1-09%	5-04%	0-00%	0-00%	0-00%	2-06%	0-00%	5-06%	2-03%	0-00%	3-08%	5-14%	0-00%	6-21%	5-09%	0-00%	0-00%	40-05%	
Approved Violations	10-91%	123-96%	1-100%	15-100%	113-97%	32-94%	21-100%	73-94%	67-97%	11-100%	35-92%	30-86%	15-100%	23-79%	49-91%	32-100%	36-92%	14-100%	700-95%
Total Notices Printed	10-91%	123-96%	1-100%	15-100%	113-97%	32-94%	21-100%	73-94%	67-97%	11-100%	35-92%	30-86%	15-100%	23-79%	49-91%	32-100%	36-92%	14-100%	700-95%

Legend: (P) = Production (I) = Inoperative  
 Note: If you selected "All" from the "Approach," drop down list, the statuses reflected in this report will only indicate the current



# Customer Management Report (Ventura) All Detection Types

01-Nov-2015 to 30-Nov-2015

Operator Id: %

Category	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAM1-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL	
<b>Total Processed Incidents</b>	13	257	15	36	155	38	14	94	95	17	39	57	27	49	56	61	69	51	1143	
<b>Less Uncontrollable Factors</b>																				
Obstruction	2	22	4	1	5	1	0	1	1	0	2	2	3	2	7	1	0	3	56	
Driver Obstruction/Duckers	0	0	0	0	0	0	0	1	2	0	1	0	0	0	0	0	0	0	4	
Motor Cycle Helmet	2	7	0	1	0	1	0	1	0	1	2	3	0	1	0	0	0	0	19	
Plate Obstruction	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	0	2	
Signal Obstruction	0	0	0	0	0	1	0	0	0	0	0	0	0	1	0	0	0	0	22	
Vehicle Obstruction	0	7	0	0	1	1	1	0	1	1	0	4	0	1	4	0	1	0		
Police																				
Chation Issued manually	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
Driver Obstruction (PD)	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
Incorrect/Incarriple DMV	0	0	0	0	0	0	0	0	1	0	0	1	0	1	0	0	0	0	3	
Invalid Offense	0	1	0	0	0	2	0	0	0	0	2	0	0	0	0	2	0	0	9	
Multiple vehicles in frame	0	17	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	18	
On or Passed the Stop Bar (PD)	0	6	0	0	4	0	0	6	0	1	0	1	4	0	1	4	0	2	45	
Plate Underintifiable	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
Plate Turn On Red	0	23	0	0	0	0	0	18	5	0	0	0	0	0	0	0	0	0	60	
Sun Glare	1	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2	
Policy/Weath																				
Extended Vehicle	0	2	0	0	0	1	0	0	1	0	0	0	0	0	0	0	0	0	4	
Sun Glare	0	30	1	1	11	3	2	0	8	0	1	6	3	13	5	2	4	10	100	
Weather/Nature	0	0	0	2	1	1	0	0	0	0	0	0	0	0	0	0	0	0	5	
Registration																				
Paper Plates	0	5	0	0	3	1	1	4	5	0	0	3	1	2	4	2	1	1	33	
Wrong or No DMV	0	3	0	0	5	0	0	0	2	0	0	1	0	0	0	0	0	0	17	
Issues	5	124	5	11	32	12	4	34	26	3	8	22	11	20	21	20	12	32	402	
<b>Sub Total Violations</b>	8	133	10	25	123	26	10	60	69	14	13	35	16	29	35	41	57	19	741	
Less In Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	8	133	10	25	123	26	10	60	69	14	13	35	16	29	35	41	57	19	741	
<b>Less Rejects</b>																				
Camera																				
Face Camera Flash	0-00%	0-00%	1-10%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	1-02%	1-02%	0-00%	4-01%	
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-20%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%	
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Plate Burn Out	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-10%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%	
Rear Plate No Flash	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	1-05%	3-00%	
Video Ships	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Police																				
Driver Underintifiable Images poor	0-00%	10-08%	0-00%	0-00%	0-00%	0-00%	2-20%	0-00%	2-03%	0-00%	0-00%	6-17%	1-06%	2-07%	0-00%	0-00%	1-02%	0-00%	24-03%	
Incorrect Speed	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Total	0-00%	11-08%	1-10%	1-04%	1-01%	1-04%	5-50%	1-04%	2-03%	0-00%	1-03%	10-29%	1-06%	2-07%	0-00%	1-02%	2-04%	1-05%	41-06%	
<b>Approved Violations</b>	8-100%	122-92%	9-90%	24-96%	122-98%	25-96%	5-50%	59-98%	67-97%	14-100%	30-97%	25-71%	15-94%	27-93%	35-100%	40-98%	55-96%	18-95%	700-94%	
Generated By: TRANDALL																				
Generated On: 3/21/2016 12:22:58 PM																				

# Customer Management Report (Ventura) All Detection Types

Operator Id: %

Operator Id	%
VE-BRJO-01	8-100%
VE-CATH-01	122-92%
VE-FOVI-01	9-90%
VE-JONB-01	24-96%
VE-MA10-01	122-99%
VE-MALE-01	25-96%
VE-MAMI-01	5-50%
VE-MIDE-01	59-98%
VE-MITG-01	67-97%
VE-TGDA-01	14-100%
VE-THSE-01	30-97%
VE-VIMC-01	25-71%
VE-VIOP-01	15-94%
VE-VIRA-01	27-93%
VE-VITG-01	35-100%
VE-VITP-01	40-98%
VE-VITP-03	55-96%
VE-VIVA-01	18-96%
TOTAL	700-94%

Legend: (P) = Production (I) = Inoperative  
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

# Customer Management Report (Ventura) All Detection Types

01-Dec-2015 to 31-Dec-2015

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
<b>Total Processed Incidents</b>	13	252	7	24	130	35	45	95	81	8	55	57	18	44	42	68	74	52	1100
<b>Less Uncontrollable Factors</b>																			
Obstruction	0	21	0	1	1	7	2	2	1	0	1	5	2	3	6	4	0	0	59
Driver Obstruction/Duckers	0	1	0	0	1	0	0	0	0	0	5	0	0	0	0	0	0	0	8
Motor Cycle Helmet	0	0	0	0	0	2	1	1	0	0	1	3	0	0	0	0	0	0	10
Plate Obstruction	1	10	0	0	4	0	5	0	0	0	2	1	1	0	1	1	1	1	28
Vehicle Obstruction	0	2	0	0	2	0	1	0	0	1	0	1	0	0	0	0	0	0	8
Police Rejects	1	1	0	0	1	0	1	0	0	0	0	0	0	0	0	1	0	0	5
Driver Obstruction (PD)	1	1	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0	3
Incomplete DMV	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	3
Invalid Offense	0	7	0	0	0	0	2	0	0	0	0	0	0	0	1	0	0	0	10
Multiple Vehicles in frame	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
On or Passed the Stop Bar (PD)	1	8	0	2	2	0	0	6	3	1	7	2	2	0	0	12	11	6	61
Plate Obstruction (PD)	0	1	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	7
Plate Unidentifiable	0	1	0	0	1	0	2	0	0	0	0	0	0	0	0	0	0	0	4
Police Discretion	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Police Turn On Red	0	19	0	0	0	0	0	21	3	0	0	0	0	0	0	0	0	0	47
Sun Glare	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Expanded Vehicle	0	3	0	0	1	0	0	0	2	0	0	2	0	0	0	0	0	0	8
Policy/Weather	0	36	1	2	3	6	2	0	2	0	2	9	5	9	5	2	1	1	93
Sun Glare	0	0	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	2
Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Registration	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Cut of Country Plate	0	4	0	4	1	0	1	4	6	2	0	4	0	0	0	0	0	0	36
Paper Plates	0	3	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	3
Whrong or No DMV	0	119	1	11	22	16	17	36	19	5	18	27	10	16	17	25	19	27	408
<b>Total</b>	3	119	1	11	22	16	17	36	19	5	18	27	10	16	17	25	19	27	408
<b>Sub Total Violations</b>	10	133	6	13	108	19	28	59	62	3	37	30	8	28	25	43	55	25	692
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	10	133	6	13	108	19	28	59	62	3	37	30	8	28	25	43	55	25	692
<b>Less Rejects</b>																			
Camera	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.03%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
Face Camera Focus Blurry	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
Malfunction	0.00%	0.00%	0.00%	0.00%	0.00%	1.05%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
Misc Camera Issue	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.04%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
Rear Image No Flash	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	2.03%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	2.00%
Scene Image No Flash	1.10%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
Test Pattern	0.00%	13.10%	0.00%	1.01%	0.00%	0.00%	0.00%	1.02%	1.02%	0.00%	0.00%	5.17%	0.00%	2.07%	0.00%	1.42%	0.00%	1.44%	25.04%
Driver Unidentifiable Images poor	0.00%	1.01%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
Incorrect Speed	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
No Video	0.00%	0.00%	0.00%	0.00%	0.00%	1.05%	1.04%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	3.00%
Plate Unclear	0.00%	0.00%	0.00%	0.00%	0.00%	1.04%	1.04%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	3.00%
Unclear Scene Image	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	2.07%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	2.00%

# Customer Management Report (Ventura) All Detection Types

Operator Id: %

	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAM-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total	1-10%	14-11%	0-00%	0-00%	1-01%	2-11%	2-07%	3-05%	1-02%	0-00%	0-00%	9-30%	0-00%	2-07%	0-00%	1-02%	0-00%	2-03%	39-05%
Approved Violations	9-90%	119-89%	6-100%	13-100%	107-99%	17-89%	26-93%	56-95%	61-98%	3-100%	37-100%	21-70%	8-100%	26-93%	25-100%	42-98%	55-100%	23-92%	654-95%
Total Notices Printed	9-90%	119-89%	6-100%	13-100%	107-99%	17-89%	26-93%	56-95%	61-98%	3-100%	37-100%	21-70%	8-100%	26-93%	25-100%	42-98%	55-100%	23-92%	654-95%

Legend: (P) = Production (I) = Inoperative  
 Note: If you selected "All" from the "Approach," drop down list, the statuses reflected in this report will only indicate the current