

# Customer Management Report (Culver City) All Detection Types

01-Jul-2010 to 30-Jun-2011

Operator Id: %

		CC-CEWA-01	CC-CIWA-01	CC-JECC-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WAGE-01	CC-WAHE-01	CC-WAHE-03	CC-MASA-01	TOTAL
Total Processed Incidents		830	2033	1419	1839	879	2569	1925	882	1900	1542	461	769	1318	1355	19721
Less Uncontrollable Factors																
Obstruction	Driver Obstruction/Duckers	0	7	0	3	2	8	1	1	2	4	0	0	1	1	30
	Plate Obstruction	9	20	7	11	11	80	7	22	25	39	7	5	5	8	256
	Vehicle Obstruction	1	1	5	2	4	22	2	1	8	8	1	1	4	1	61
Police Rejects	Driver ID - Poor Driver Image -	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
	Driver ID - Poor Driver Image -	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
	Driver Obstruction (PD)	1	40	15	10	7	44	16	7	11	8	8	1	3	11	182
	Driver Obstruction - Duckers	0	0	1	0	1	0	0	0	0	0	0	0	0	0	2
	Emergency Vehicle Responding	247	154	79	126	54	25	227	182	102	66	20	16	16	54	1368
	Funeral Procession/Police	0	0	0	2	0	0	451	0	0	0	0	0	0	0	453
	Incorrect Plate on Vehicle	0	2	0	0	0	0	0	0	0	0	0	0	0	1	3
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1
	Multiple vehicles in frame	3	20	8	4	0	37	3	5	3	7	0	3	13	1	107
	No Plates	1	11	5	5	0	12	10	2	6	4	0	2	1	7	66
	Non Violation - Green Light	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
	Non Violation - Vehicle Behind	0	0	0	0	1	1	0	0	0	0	0	0	0	1	3
	On or Passed the Stop Bar (PD)	28	14	7	7	24	72	17	20	43	65	23	2	8	4	334
	Plate Obstruction (PD)	0	0	0	0	1	2	2	0	4	2	0	0	1	2	14
	Plate Unidentifiable	22	55	50	69	22	84	61	36	77	55	25	26	36	138	756
	Police Discretion	119	190	70	192	109	60	193	32	85	28	42	107	18	299	1544
	Straight Thru On Left	0	0	5	0	0	6	1	0	0	0	0	0	0	1	13
Vehicle Obstruction	1	25	10	1	4	31	7	8	12	8	0	3	15	4	129	
Yielding to an Emergency	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Policy/Weather	Extended Vehicle	0	0	5	2	1	3	1	4	1	0	3	0	0	3	23
	Sun Glare	0	0	0	0	1	9	2	1	6	3	1	1	1	3	28
	Weather/Nature	0	0	0	1	1	0	0	0	0	0	0	0	0	0	2
Registration Issues	Out of Country Plate	0	0	0	3	0	2	0	0	2	0	0	3	0	1	11
	Paper Plates	0	2	0	1	0	0	0	0	3	1	0	0	0	1	8
	Wrong or No DMV	0	1	0	0	0	0	0	0	0	0	1	0	0	2	4
Total		432	542	267	439	244	498	1001	322	390	298	131	170	122	545	5401
Sub Total Violations		398	1491	1152	1400	635	2071	924	560	1510	1244	330	599	1196	810	14320
Less in Progress		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution		398	1491	1152	1400	635	2071	924	560	1510	1244	330	599	1196	810	14320
Less Rejects																
Camera Malfunction	Face Not in Frame	1-00%	4-00%	5-00%	0-00%	0-00%	3-00%	2-00%	1-00%	5-00%	7-01%	2-01%	0-00%	0-00%	6-01%	36-00%
Camera Malfunction	Image Missing	1-00%	1-00%	0-00%	0-00%	0-00%	3-00%	0-00%	9-02%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	15-00%

Generated By: OCORRALES

Generated On: 11/4/2011 11:40:54 AM

# Customer Management Report (Culver City) All Detection Types

01-Jul-2010 to 30-Jun-2011

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WAGE-01	CC-WAHE-01	CC-WAHE-03	CC-MASA-01	TOTAL
Misc Camera Issue	0-00%	0-00%	0-00%	4-00%	0-00%	41-02%	0-00%	0-00%	3-00%	2-00%	0-00%	0-00%	0-00%	0-00%	50-00%
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	9-01%	14-00%
Plate Not in Frame	0-00%	0-00%	7-01%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%	1-00%	1-00%	0-00%	1-00%	0-00%	12-00%
Rear Plate Camera Blurry	0-00%	0-00%	6-01%	0-00%	0-00%	0-00%	1-00%	1-00%	8-01%	3-00%	1-00%	1-00%	0-00%	1-00%	22-00%
Rear Plate Flash Inappropriate	1-00%	2-00%	0-00%	0-00%	0-00%	19-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	22-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	2-00%
Scene Image No Flash	0-00%	1-00%	0-00%	1-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	5-00%
Police Rejects															
Driver Unidentifiable images poor	31-08%	83-06%	45-04%	57-04%	68-11%	94-05%	91-10%	63-11%	30-02%	52-04%	39-12%	32-05%	19-02%	66-08%	770-05%
Equipment Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%
No Images	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Plate Unclear	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Sun Glare	10-03%	23-02%	0-00%	5-00%	9-01%	36-02%	55-06%	2-00%	42-03%	30-02%	2-01%	4-01%	14-01%	22-03%	254-02%
Unclear Scene Image	11-03%	9-01%	18-02%	5-00%	10-02%	108-05%	16-02%	9-02%	9-01%	7-01%	5-02%	7-01%	5-00%	15-02%	234-02%
Total	55-14%	125-08%	81-07%	72-05%	89-14%	308-15%	170-18%	85-15%	100-07%	103-08%	50-15%	44-07%	40-03%	121-15%	1443-10%
Approved Violations	343-86%	1366-92%	1071-93%	1328-95%	546-86%	1763-85%	754-82%	475-85%	1410-93%	1141-92%	280-85%	555-93%	1156-97%	689-85%	12877-90%
Total Notices Printed	343-86%	1366-92%	1071-93%	1328-95%	546-86%	1763-85%	754-82%	475-85%	1410-93%	1141-92%	280-85%	555-93%	1156-97%	689-85%	12877-90%