

Customer Management Report (Loma Linda) Redlight Incidents

01-Aug-2006 to 31-Aug-2006

Operator Id: %

	LOM-ANBA-0	LOM-BAAN-0	LOM-BAMC-	LOM-MOBA-	LOM-REAN-0	LOM-REAN-0	LOM-REMO-	TOTAL
Total Violations	177	353	150	472	375	187	218	1932
Available For Prosecution	97	274	98	292	237	120	152	1270
Less Rejects								
Camera Malfunction	0-00%	0-00%	2-02%	3-01%	0-00%	0-00%	0-00%	5-00%
Digital Distortion	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	0-00%	2-00%
Face Camera Flash	1-01%	0-00%	0-00%	5-02%	0-00%	0-00%	0-00%	6-00%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	1-00%	1-00%	0-00%	1-01%	3-00%
Face Camera No Flash								
Face Not In Frame	0-00%	0-00%	0-00%	2-01%	2-01%	0-00%	0-00%	4-00%
Image Missing	0-00%	1-00%	0-00%	29-10%	1-00%	0-00%	1-01%	32-03%
Misc Camera Issue	0-00%	0-00%	0-00%	40-14%	0-00%	0-00%	1-01%	41-03%
Plate Burn Out	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-01%	2-00%
Plate Not In Frame	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	1-01%	3-00%
Rear Plate Camera Blurry	0-00%	0-00%	3-03%	0-00%	0-00%	1-01%	0-00%	6-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	2-01%	1-00%	0-00%	0-00%	1-00%
Scene Image No Flash	0-00%	3-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Redlight not visible in	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Vehicle On or Passed Stop Line	1-01%	5-02%	7-07%	82-28%	7-03%	4-03%	5-03%	111-09%
Total	96-99%	269-98%	91-93%	210-72%	230-97%	116-97%	147-97%	1159-91%

Notices Printed

Customer Management Report (Loma Linda) Redlight Incidents

01-Sep-2006 to 30-Sep-2006

Operator Id: %

	LOM-ANBA-0	LOM-BAAN-0	LOM-BAMO-	LOM-MOBA-	LOM-REAN-0	LOM-REAN-0	LOM-REMO-	TOTAL
Total Violations	204	270	144	411	338	195	200	1762
Available For Prosecution	112	187	79	196	119	119	136	1024
Less Rejects								
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	3-00%
Digital Distortion	1-01%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	3-00%
Face Camera Flash	2-02%	0-00%	3-04%	7-04%	1-01%	1-01%	0-00%	14-01%
Face Camera Focus Blurry	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	2-00%
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	2-01%	4-00%
Face Not in Frame	0-00%	3-02%	0-00%	2-01%	2-01%	1-01%	0-00%	9-01%
Image Missing	1-01%	0-00%	0-00%	3-02%	0-00%	0-00%	1-01%	6-01%
Misc Camera Issue	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	2-00%
Plate Burn Out	3-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%
Plate Not in Frame	0-00%	0-00%	1-01%	1-01%	1-01%	1-01%	1-01%	5-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	4-02%	1-01%	0-00%	0-00%	0-00%	0-00%	5-00%
Scene Image No Flash	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	2-00%
Driver Unidentifiable images poor	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Rejects	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
No Video	0-00%	0-00%	0-00%	0-00%	2-01%	1-01%	1-01%	4-00%
Red-light not visible in	1-01%	2-01%	0-00%	0-00%	2-01%	0-00%	2-01%	7-01%
Unclear Scene Image	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	2-00%
Vehicle On or Passed Stop Line	11-10%	11-06%	8-10%	17-09%	14-07%	6-05%	8-06%	75-07%
Total	101-90%	176-94%	71-90%	179-91%	181-93%	113-95%	128-94%	949-93%
Notices Printed								

Customer Management Report (Loma Linda) Redlight Incidents

01-Oct-2006 to 31-Oct-2006
Operator Id: %

	LOM-ANBA-0	LOM-BAAN-0	LOM-BAMO-	LOM-MOBA-	LOM-REAN-0	LOM-FEAN-0	LOM-REMO-	TOTAL
Total Violations	228	368	151	423	365	213	208	1956
Available For Prosecution	137	273	88	238	216	127	144	1223
Less Rejects								
Camera Malfunction	23-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	23-02%
Face Camera Flash	2-01%	0-00%	0-00%	3-01%	0-00%	2-02%	1-01%	8-01%
Face Camera Focus Blurry	0-00%	1-00%	8-09%	6-03%	2-01%	2-02%	1-01%	20-02%
Face Camera No Flash	1-01%	0-00%	0-00%	1-00%	0-00%	2-02%	0-00%	4-00%
Face Not in Frame	0-00%	1-00%	1-01%	0-00%	1-00%	1-01%	0-00%	4-00%
Image Missing	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	8-06%	0-00%	0-00%	0-00%	1-00%	0-00%	2-01%	11-01%
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	3-01%	0-00%	2-02%	1-01%	6-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	1-01%	0-00%	0-00%	3-02%	0-00%	4-00%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%
Police Rejects								
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	2-00%
Vehicle On or Passed Stop Line	1-01%	9-03%	1-01%	3-01%	0-00%	0-00%	5-03%	19-02%
Total	36-26%	12-04%	11-12%	17-07%	5-02%	15-12%	12-08%	108-09%
Notices Printed	101-74%	261-96%	77-86%	221-93%	211-98%	112-88%	132-92%	1115-91%

Customer Management Report (Loma Linda) Redlight Incidents

01-Nov-2006 to 30-Nov-2006

Operator Id: %

	LOM-ANBA-0	LOM-BAAN-0	LOM-BAMO-	LOM-MOBA-	LOM-REAN-0	LOM-REAN-0	LOM-REMO-	TOTAL
Total Violations	192	199	104	388	334	163	172	1552
Available For Prosecution	124	149	68	229	219	108	123	1020
Less Rejects								
Camera	0-00%	0-00%	0-00%	4-02%	1-00%	1-01%	0-00%	6-01%
Face Camera Flash	2-02%	0-00%	1-01%	10-04%	2-01%	1-01%	1-01%	17-02%
Malfunction	4-03%	2-01%	0-00%	1-00%	0-00%	0-00%	0-00%	7-01%
Image Missing								
Police Rejects								
Misc Camera Issue	10-08%	1-01%	1-01%	0-00%	0-00%	0-00%	0-00%	12-01%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	3-01%	1-00%	1-01%	1-01%	6-01%
Scene Image Flash Inappropriate	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Scene Image No Flash	6-05%	2-01%	2-03%	0-00%	1-00%	1-01%	0-00%	12-01%
Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
Process Issues								
Red-light not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	2-00%
Vehicle On or Passed Stop Line	0-00%	1-01%	2-03%	1-00%	0-00%	1-01%	1-01%	6-01%
Too Old	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%
Total	22-18%	7-05%	6-09%	20-09%	6-03%	7-06%	3-02%	71-07%
Notices Printed	102-82%	142-95%	62-91%	209-91%	213-97%	101-94%	120-98%	949-93%

Customer Management Report (Loma Linda) Redlight Incidents

01-Dec-2006 to 31-Dec-2006 Operator Id: %

LOM-ANBA-0 LOM-BAAN-0 LOM-BAIMO- LOM-MOBA- LOM-REAN-0 LOM-REAN-0 LOM-REMO- TOTAL

	168	111	51	302	302	130	92	1156
Total Violations	168	111	51	302	302	130	92	1156
Available For Prosecution	116	88	23	180	230	99	58	794
Less Rejects	0-00%	0-00%	0-00%	0-00%	5-02%	0-00%	0-00%	5-01%
Camera Malfunction	0-00%	1-01%	0-00%	5-03%	0-00%	0-00%	0-00%	6-01%
Face Camera Flash	3-03%	0-00%	0-00%	9-05%	1-00%	1-01%	1-02%	15-02%
Face Camera Focus Blurry	0-00%	0-00%	0-00%	4-02%	0-00%	0-00%	0-00%	4-01%
Face Camera No Flash	0-00%	0-00%	0-00%	1-01%	1-00%	0-00%	0-00%	2-00%
Face Not in Frame								
Image Missing	6-05%	3-03%	0-00%	0-00%	5-02%	1-01%	0-00%	15-02%
Misc Camera Issue	5-04%	0-00%	0-00%	0-00%	13-06%	0-00%	0-00%	18-02%
Rear Plate Camera Blurry	1-01%	0-00%	0-00%	0-00%	1-00%	1-01%	1-02%	4-01%
Rear Plate Flash Inappropriate	2-02%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	3-00%
Rear Plate No Flash	1-01%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image Flash Inappropriate	0-00%	1-01%	0-00%	15-08%	0-00%	0-00%	0-00%	16-02%
Scene Image No Flash	0-00%	0-00%	0-00%	27-15%	1-00%	0-00%	0-00%	28-04%
Driver Unidentifiable Images poor	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
No Video	0-00%	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	2-00%
Red-light not visible in	0-00%	0-00%	1-04%	0-00%	0-00%	1-01%	0-00%	2-00%
Total	18-16%	6-07%	2-09%	63-35%	27-12%	5-05%	2-03%	123-15%
Notices Printed	98-84%	82-93%	21-91%	117-65%	203-88%	94-95%	56-97%	671-85%

Customer Management Report (Loma Linda) Redlight Incidents

01-Apr-2010 to 30-Apr-2010

Operator Id: %

	LOM-ANBA-0	LOM-BAAN-0	LOM-BAMO-	LOM-MOBA-	LOM-REAN-0	LOM-REAN-0	LOM-REAN-0	LOM-REMO-	TOTAL
Total Violations	246	0	13	345	27	13	10	654	
Available For Prosecution	102	0	2	113	6	9	4	236	
Less Rejects									
Camera Malfunction	1-01%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	3-01%	
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	1-00%	
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	1-11%	0-00%	1-00%	
Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	2-22%	0-00%	2-01%	
Rear Plate Flash Inappropriate									
Police Rejects	5-05%	0-00%	0-00%	6-05%	1-17%	0-00%	0-00%	12-05%	
Red-light not visible in	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Total	7-07%	0-00%	0-00%	8-07%	1-17%	4-44%	0-00%	20-08%	
Notices Printed	95-93%	0-00%	2-100%	105-93%	5-83%	5-56%	4-100%	216-92%	

Customer Management Report (Loma Linda) Redlight Incidents

01-May-2010 to 31-May-2010

Operator Id: %

LOM-ANBA-0 LOM-BAAN-0 LOM-BAMO- LOM-MOBA- LOM-REAN-0 LOM-REAN-0 LOM-REMO- TOTAL

	225	15	12	244	29	27	9	561
Total Violations	83	8	7	81	13	12	2	206
Available For Prosecution								
Less Rejects								
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	1-08%	0-00%	0-00%	1-00%
Face Not in Frame	0-00%	0-00%	1-14%	0-00%	0-00%	6-50%	0-00%	7-03%
Plate Burn Out	0-00%	0-00%	1-14%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Camera Blurry								
Police Rejects	1-01%	0-00%	0-00%	3-04%	0-00%	0-00%	0-00%	4-02%
Process Issues	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	2-02%	0-00%	2-29%	3-04%	1-08%	6-50%	0-00%	14-07%
Notices Printed	81-98%	8-100%	5-71%	78-96%	12-92%	6-50%	2-100%	152-93%

Customer Management Report (Loma Linda) Redlight Incidents

01-Jun-2010 to 30-Jun-2010

Operator Id: %

LOM-ANBA-0 LOM-BAAN-0 LOM-BAMO- LOM-MOBA- LOM-REAN-0 LOM-REAN-0 LOM-REMO- TOTAL

	136	21	18	345	30	20	10	580
Total Violations	136	21	18	345	30	20	10	580
Available For Prosecution	50	10	7	140	7	14	4	232
Less Rejects								
Camera	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Face Camera Flash	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Face Camera Focus Blurry	0-00%	0-00%	3-43%	2-01%	0-00%	0-00%	0-00%	5-02%
Face Not in Frame	0-00%	0-00%	0-00%	7-05%	0-00%	0-00%	0-00%	7-03%
Misc Camera Issue								
Plate Burn Out	0-00%	0-00%	0-00%	0-00%	0-00%	4-29%	0-00%	4-02%
Plate Not in Frame	0-00%	0-00%	1-14%	1-01%	0-00%	0-00%	0-00%	2-01%
Driver Unidentifiable Images poor	0-00%	0-00%	0-00%	0-00%	1-14%	0-00%	0-00%	1-00%
Police Rejects								
Red-light not visible in	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	1-02%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	2-01%
Total	2-04%	0-00%	4-57%	13-09%	1-14%	4-29%	0-00%	24-10%
Notices Printed	48-96%	10-100%	3-43%	127-91%	6-86%	10-71%	4-100%	208-90%

Customer Management Report (Loma Linda) Redlight Incidents

01-Jul-2010 to 31-Jul-2010 Operator Id: %

	LOM-ANBA-0	LOM-BAAN-0	LOM-BAMO-	LOM-MOBA-	LOM-REAN-0	LOM-REAN-0	LOM-REMO-	TOTAL
Total Violations	223	13	16	527	38	19	15	851
Available For Prosecution	101	8	8	195	10	9	7	338
Less Rejects								
Camera Malfunction	3-03%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-01%
Face Camera Focus Blurry	0-00%	0-00%	1-12%	3-02%	0-00%	0-00%	0-00%	4-01%
Face Not in Frame	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out								
Plate Not in Frame	0-00%	0-00%	1-12%	0-00%	0-00%	0-00%	0-00%	1-00%
Driver Unidentifiable images poor	6-06%	0-00%	0-00%	7-04%	2-20%	0-00%	2-29%	17-05%
Red-light not visible in Sun Glare	0-00%	1-12%	1-12%	0-00%	0-00%	1-11%	0-00%	3-01%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	2-20%	0-00%	0-00%	2-01%
	9-09%	1-12%	4-50%	11-06%	4-40%	1-11%	2-29%	32-09%
Total	92-31%	7-88%	4-50%	184-94%	6-60%	8-85%	5-71%	306-91%
Notices Printed								