

# Customer Management Report (San Mateo) All Detection Types

01-Mar-2007 to 31-Mar-2007

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
<b>Total Processed Incidents</b>		330	87	163	104	558	1242
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	24	3	8	2	43	80
	Motor Cycle Helmet	1	0	0	0	0	1
	Plate Obstruction	8	0	11	6	55	80
	Vehicle Obstruction	2	0	5	1	12	20
Police Rejects	Emergency Vehicle Responding	1	6	2	5	4	18
	Invalid Offense	0	0	0	0	1	1
	Multiple vehicles in frame	0	0	0	0	1	1
	Safe Turn On Red	0	0	11	0	74	85
	Sun Glare	2	0	1	0	1	4
Policy/Weather	Extended Vehicle	1	0	1	0	0	2
	Sun Glare	42	4	14	6	5	71
	Weather/Nature	2	0	0	1	1	4
Registration Issues	Can Not Identify State	1	0	0	0	0	1
	Paper Plates	11	2	3	5	18	39
	Wrong or No DMV	0	0	3	1	5	9
<b>Total</b>		95	15	59	27	220	416
<b>Sub Total Violations</b>		235	72	104	77	338	826
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		235	72	104	77	338	826
<b>Less Rejects</b>							
Camera Malfunction	Databar Unreadable/Incorrect	0-00%	2-03%	0-00%	0-00%	0-00%	2-00%
	Face Camera Flash	0-00%	0-00%	1-01%	0-00%	1-00%	2-00%
	Face Camera Focus Blurry	1-00%	0-00%	2-02%	1-01%	2-01%	6-01%
	Face Camera No Flash	36-15%	0-00%	1-01%	0-00%	1-00%	38-05%
	Image Missing	0-00%	0-00%	0-00%	0-00%	52-15%	52-06%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	16-05%	16-02%
	Plate Burn Out	1-00%	1-01%	0-00%	0-00%	0-00%	2-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	2-01%	2-00%
	Rear Plate Camera Blurry	3-01%	0-00%	1-01%	3-04%	0-00%	7-01%
	Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-01%	0-00%	1-00%
	Rear Plate No Flash	1-00%	0-00%	0-00%	0-00%	1-00%	2-00%
Scene Image Flash Inappropriate	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Police Rejects	Driver Unidentifiable images poor	6-03%	0-00%	6-06%	1-01%	1-00%	14-02%
	Plate Unclear	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Unclear Scene Image	5-02%	1-01%	0-00%	0-00%	0-00%	6-01%

Generated By: MCARROLL

Generated On: 7/1/2015 11:32:37 AM

# Customer Management Report (San Mateo) All Detection Types

01-Mar-2007 to 31-Mar-2007

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total	54-23%	4-06%	11-11%	6-08%	77-23%	152-18%
Approved Violations	181-77%	68-94%	93-89%	71-92%	261-77%	674-82%
Total Notices Printed	181-77%	68-94%	93-89%	71-92%	261-77%	674-82%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:32:37 AM

# Customer Management Report (San Mateo) All Detection Types

01-Sep-2007 to 30-Sep-2007

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
<b>Total Processed Incidents</b>		350	59	163	38	440	1050
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	32	4	8	2	22	68
	Motor Cycle Helmet	2	0	0	0	1	3
	Plate Obstruction	4	2	7	4	16	33
	Vehicle Obstruction	5	0	3	2	25	35
Police Rejects	Emergency Vehicle Responding	4	1	1	0	0	6
	Incorrect Plate on Vehicle	1	0	0	1	1	3
	Plate Unidentifiable	0	1	0	0	0	1
	Safe Turn On Red	0	0	10	0	32	42
Policy/Weather	Extended Vehicle	1	0	1	0	0	2
	Sun Glare	34	11	9	7	22	83
Registration Issues	Can Not Identify State	0	0	0	1	0	1
	Paper Plates	7	0	1	1	11	20
	Wrong or No DMV	1	0	1	0	0	2
<b>Total</b>		91	19	41	18	130	299
<b>Sub Total Violations</b>		259	40	122	20	310	751
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		259	40	122	20	310	751
<b>Less Rejects</b>							
Camera Malfunction	Face Camera Focus Blurry	3-01%	2-05%	0-00%	0-00%	0-00%	5-01%
	Face Camera No Flash	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
	Image Missing	7-03%	0-00%	1-01%	0-00%	0-00%	8-01%
	Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	97-31%	97-13%
	Plate Burn Out	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Rear Plate Camera Blurry	1-00%	0-00%	4-03%	0-00%	0-00%	5-01%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	No Video	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Process Issues	Too Old	0-00%	1-02%	0-00%	0-00%	0-00%	1-00%
<b>Total</b>		12-05%	4-10%	5-04%	0-00%	102-33%	123-16%
<b>Approved Violations</b>		247-95%	36-90%	117-96%	20-100%	208-67%	628-84%
<b>Total Notices Printed</b>		247-95%	36-90%	117-96%	20-100%	208-67%	628-84%

Generated By: MCARROLL

Generated On: 7/1/2015 11:33:47 AM

# Customer Management Report (San Mateo) All Detection Types

01-Sep-2007 to 30-Sep-2007

Operator Id: %

---

TOTAL	SAN-SAHI-01	SAN-HISA-01	SAN-HINO-03	SAN-HINO-01	SAN-4HU-01
-------	-------------	-------------	-------------	-------------	------------

---

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:33:47 AM

# Customer Management Report (San Mateo) All Detection Types

01-Mar-2008 to 31-Mar-2008

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL	
<b>Total Processed Incidents</b>	296	59	134	65	491	1045	
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	24	3	4	4	22	57
	Motor Cycle Helmet	0	0	0	0	1	1
	Plate Obstruction	7	0	5	1	8	21
	Vehicle Obstruction	6	0	3	0	20	29
Police Rejects	Emergency Vehicle Responding	7	4	1	4	6	22
	Multiple vehicles in frame	0	0	1	0	2	3
	Plate Unidentifiable	0	0	0	0	1	1
	Safe Turn On Red	0	0	3	0	86	89
Policy/Weather	Extended Vehicle	0	0	0	1	0	1
	Sun Glare	19	7	6	4	0	36
	Weather/Nature	7	1	2	6	2	18
	Yellow with Red Light	1	0	0	0	0	1
Registration Issues	Paper Plates	10	2	1	1	10	24
<b>Total</b>		81	17	26	21	158	303
<b>Sub Total Violations</b>		215	42	108	44	333	742
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		215	42	108	44	333	742
<b>Less Rejects</b>							
Camera Malfunction	Face Camera Flash	0-00%	0-00%	1-01%	1-02%	0-00%	2-00%
	Face Camera Focus Blurry	1-00%	1-02%	0-00%	0-00%	1-00%	3-00%
	Image Missing	0-00%	2-05%	0-00%	0-00%	1-00%	3-00%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Rear Plate Camera Blurry	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
	Scene Image No Flash	0-00%	0-00%	0-00%	3-07%	0-00%	3-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	No Images	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Unclear Scene Image	0-00%	0-00%	2-02%	0-00%	1-00%	3-00%
	Vehicle On or Passed Stop Line	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
Process Issues	Too Old	2-01%	0-00%	0-00%	0-00%	0-00%	2-00%
<b>Total</b>		4-02%	3-07%	5-05%	4-09%	5-02%	21-03%
<b>Approved Violations</b>		211-98%	39-93%	103-95%	40-91%	328-98%	721-97%
<b>Total Notices Printed</b>		211-98%	39-93%	103-95%	40-91%	328-98%	721-97%

Generated By: MCARROLL

Generated On: 7/1/2015 11:34:58 AM

# Customer Management Report (San Mateo) All Detection Types

01-Mar-2008 to 31-Mar-2008

Operator Id: %

---

TOTAL	SAN-SAHI-01	SAN-HISA-01	SAN-HINO-03	SAN-HINO-01	SAN-4HU-01
-------	-------------	-------------	-------------	-------------	------------

---

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:34:58 AM

# Customer Management Report (San Mateo) All Detection Types

01-Sep-2008 to 30-Sep-2008

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
<b>Total Processed Incidents</b>		247	54	121	57	560	1039
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	16	0	3	1	13	33
	Motor Cycle Helmet	0	0	0	0	2	2
	Plate Obstruction	12	4	2	1	47	66
	Vehicle Obstruction	1	0	1	1	23	26
Police Rejects	Emergency Vehicle Responding	7	2	0	2	2	13
	Incorrect Plate on Vehicle	0	0	0	0	2	2
	Invalid Offense	0	0	1	0	11	12
	Plate Unidentifiable	1	0	0	0	1	2
	Safe Turn On Red	1	0	10	0	109	120
	Sun Glare	0	0	1	0	0	1
	Policy/Weather	Extended Vehicle	1	0	0	1	2
	Sun Glare	30	13	5	12	23	83
	Weather/Nature	0	0	2	0	0	2
Registration Issues	Can Not Identify State	0	0	1	0	2	3
	Out of Country Plate	0	0	0	0	1	1
	Paper Plates	9	1	7	2	20	39
	Wrong or No DMV	0	0	0	1	3	4
<b>Total</b>		78	20	33	21	261	413
<b>Sub Total Violations</b>		169	34	88	36	299	626
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		169	34	88	36	299	626
<b>Less Rejects</b>							
Camera Malfunction	Digital Distortion	0-00%	0-00%	0-00%	1-03%	0-00%	1-00%
	Face Camera Flash	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	2-01%	0-00%	5-06%	1-03%	2-01%	10-02%
	Face Not in Frame	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Image Missing	0-00%	0-00%	0-00%	1-03%	0-00%	1-00%
	Misc Camera Issue	1-01%	0-00%	0-00%	3-08%	0-00%	4-01%
	Plate Burn Out	6-04%	1-03%	0-00%	0-00%	0-00%	7-01%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	3-01%	3-00%
	Rear Plate Camera Blurry	7-04%	0-00%	2-02%	1-03%	1-00%	11-02%
	Rear Plate Flash Inappropriate	2-01%	0-00%	1-01%	0-00%	1-00%	4-01%
Scene Image Flash Inappropriate	7-04%	0-00%	0-00%	0-00%	13-04%	20-03%	
Police Rejects	Unclear Scene Image	0-00%	0-00%	1-01%	0-00%	1-00%	2-00%

Generated By: MCARROLL

Generated On: 7/1/2015 11:35:31 AM

# Customer Management Report (San Mateo) All Detection Types

01-Sep-2008 to 30-Sep-2008

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total	25-15%	2-06%	9-10%	7-19%	22-07%	65-10%
Approved Violations	144-85%	32-94%	79-90%	29-81%	277-93%	561-90%
Total Notices Printed	144-85%	32-94%	79-90%	29-81%	277-93%	561-90%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:35:31 AM



# Customer Management Report (San Mateo) All Detection Types

01-Mar-2009 to 31-Mar-2009

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
<b>Total Processed Incidents</b>		170	25	94	34	655	978
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	17	0	11	0	14	42
	Plate Obstruction	7	1	3	3	71	85
	Vehicle Obstruction	1	0	0	1	17	19
Police Rejects	Emergency Vehicle Responding	4	2	1	1	5	13
	Plate Unidentifiable	2	0	0	0	0	2
	Safe Turn On Red	1	0	7	0	163	171
	Sun Glare	0	0	1	0	0	1
Policy/Weather	Sun Glare	11	2	3	4	7	27
	Weather/Nature	2	1	1	0	1	5
Registration Issues	Can Not Identify State	1	0	0	0	0	1
	Out of Country Plate	0	0	0	0	1	1
	Paper Plates	2	0	3	0	13	18
	Wrong or No DMV	1	0	0	0	1	2
<b>Total</b>		49	6	30	9	293	387
<b>Sub Total Violations</b>		121	19	64	25	362	591
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		121	19	64	25	362	591
<b>Less Rejects</b>							
Camera Malfunction	Face Camera Flash	0-00%	1-05%	0-00%	0-00%	0-00%	1-00%
	Face Camera Focus Blurry	0-00%	0-00%	2-03%	0-00%	2-01%	4-01%
	Image Missing	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Plate Burn Out	0-00%	1-05%	0-00%	0-00%	0-00%	1-00%
	Plate Not in Frame	0-00%	0-00%	8-12%	0-00%	2-01%	10-02%
	Rear Plate Camera Blurry	0-00%	2-11%	0-00%	0-00%	3-01%	5-01%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	2-01%	2-00%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
<b>Total</b>		0-00%	4-21%	10-16%	0-00%	11-03%	25-04%
<b>Approved Violations</b>		121-100%	15-79%	54-84%	25-100%	351-97%	566-96%
<b>Total Notices Printed</b>		121-100%	15-79%	54-84%	25-100%	351-97%	566-96%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:36:32 AM

# Customer Management Report (San Mateo) All Detection Types

01-Sep-2009 to 30-Sep-2009

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
<b>Total Processed Incidents</b>	207	33	86	28	489	843
<b>Less Uncontrollable Factors</b>						
Obstruction						
Driver Obstruction/Duckers	15	1	4	1	14	35
Motor Cycle Helmet	1	0	0	0	1	2
Plate Obstruction	13	4	2	1	58	78
Vehicle Obstruction	2	2	3	1	23	31
Police Rejects						
Emergency Vehicle Responding	7	0	0	3	1	11
Invalid Offense	0	0	0	0	1	1
Multiple vehicles in frame	0	0	0	0	1	1
Plate Unidentifiable	0	0	0	0	1	1
Safe Turn On Red	0	0	7	0	90	97
Policy/Weather						
Sun Glare	21	5	7	7	8	48
Registration Issues						
Can Not Identify State	0	0	0	0	1	1
Paper Plates	2	0	2	2	7	13
Wrong or No DMV	0	0	0	0	1	1
<b>Total</b>	<b>61</b>	<b>12</b>	<b>25</b>	<b>15</b>	<b>207</b>	<b>320</b>
<b>Sub Total Violations</b>	<b>146</b>	<b>21</b>	<b>61</b>	<b>13</b>	<b>282</b>	<b>523</b>
Less in Progress	0	0	0	0	0	0
<b>Available For Prosecution</b>	<b>146</b>	<b>21</b>	<b>61</b>	<b>13</b>	<b>282</b>	<b>523</b>
<b>Less Rejects</b>						
Camera Malfunction						
Face Camera Flash	0-00%	1-05%	4-07%	1-08%	1-00%	7-01%
Face Camera Focus Blurry	0-00%	1-05%	5-08%	1-08%	1-00%	8-02%
Face Camera No Flash	0-00%	1-05%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	1-05%	0-00%	0-00%	0-00%	1-00%
Plate Not in Frame	0-00%	1-05%	1-02%	0-00%	0-00%	2-00%
Rear Plate Camera Blurry	2-01%	0-00%	0-00%	0-00%	1-00%	3-01%
Police Rejects						
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
<b>Total</b>	<b>2-01%</b>	<b>5-24%</b>	<b>10-16%</b>	<b>2-15%</b>	<b>4-01%</b>	<b>23-04%</b>
<b>Approved Violations</b>	<b>144-99%</b>	<b>16-76%</b>	<b>51-84%</b>	<b>11-85%</b>	<b>278-99%</b>	<b>500-96%</b>
<b>Total Notices Printed</b>	<b>144-99%</b>	<b>16-76%</b>	<b>51-84%</b>	<b>11-85%</b>	<b>278-99%</b>	<b>500-96%</b>

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:37:22 AM

# Customer Management Report (San Mateo) All Detection Types

01-Oct-2014 to 31-Oct-2014

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
<b>Total Processed Incidents</b>		100	49	166	50	792	1157
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	1	0	5	0	13	19
	Motor Cycle Helmet	1	0	0	1	3	5
	Plate Obstruction	6	0	4	0	8	18
	Vehicle Obstruction	1	1	5	2	36	45
Police Rejects	Emergency Vehicle Responding	1	1	0	4	3	9
	Funeral Procession/Police	0	4	4	2	0	10
	Multiple vehicles in frame	0	0	1	0	30	31
	On or Passed the Stop Bar (PD).	3	2	42	6	294	347
	Plate Unidentifiable	0	0	0	0	1	1
	Slow Roll - right turn	0	0	5	0	56	61
	Sun Glare	0	0	1	0	0	1
	Yielding to an Emergency	1	0	0	0	0	1
	Policy/Weather	Extended Vehicle	1	0	1	0	0
Sun Glare		7	3	4	10	20	44
Weather/Nature		0	0	0	0	1	1
Registration Issues	Paper Plates	4	2	9	4	22	41
	Wrong or No DMV	0	0	0	0	2	2
<b>Total</b>		26	13	81	29	489	638
<b>Sub Total Violations</b>		74	36	85	21	303	519
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		74	36	85	21	303	519
<b>Less Rejects</b>							
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	1-05%	1-00%	2-00%
	Face Camera Focus Blurry	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Face Not in Frame	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
	Plate Burn Out	2-03%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	9-03%	9-02%
	Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	4-01%	4-01%
	Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	2-01%	2-00%
	Unclear Scene Image	1-01%	0-00%	0-00%	0-00%	0-00%	1-00%
Process Issues	Too Old	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
<b>Total</b>		4-05%	0-00%	0-00%	1-05%	19-06%	24-05%
<b>Approved Violations</b>		70-95%	36-100%	85-100%	20-95%	284-94%	495-95%

Generated By: MCARROLL

Generated On: 7/1/2015 11:38:17 AM

# Customer Management Report (San Mateo) All Detection Types

01-Oct-2014 to 31-Oct-2014

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
Total Notices Printed	70-95%	36-100%	85-100%	20-95%	284-94%	495-95%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:38:17 AM

# Customer Management Report (San Mateo) All Detection Types

01-Nov-2014 to 30-Nov-2014

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL	
<b>Total Processed Incidents</b>	68	48	119	28	753	1016	
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	5	1	4	1	13	24
	Plate Obstruction	0	0	0	1	18	19
	Vehicle Obstruction	3	0	4	1	21	29
Police Rejects	Emergency Vehicle Responding	1	1	2	2	3	9
	Incorrect Plate on Vehicle	0	0	0	0	3	3
	Incorrect/Incomplete DMV	1	0	0	0	1	2
	Multiple vehicles in frame	0	0	0	0	17	17
	On or Passed the Stop Bar (PD).	4	3	25	4	339	375
	Slow Roll - right turn	0	0	0	0	4	4
	Sun Glare	0	0	1	0	0	1
Policy/Weather	Extended Vehicle	2	0	0	0	0	2
	Sun Glare	10	3	1	3	2	19
	Weather/Nature	0	0	2	1	5	8
Registration Issues	Paper Plates	2	3	2	0	21	28
<b>Total</b>		28	11	41	13	447	540
<b>Sub Total Violations</b>		40	37	78	15	306	476
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		40	37	78	15	306	476
<b>Less Rejects</b>							
Camera Malfunction	Face Not in Frame	1-02%	0-00%	0-00%	0-00%	0-00%	1-00%
	Misc Camera Issue	5-12%	0-00%	40-51%	0-00%	0-00%	45-09%
Police Rejects Process Issues	Driver Unidentifiable images poor	0-00%	1-03%	1-01%	0-00%	5-02%	7-01%
	Too Old	0-00%	0-00%	0-00%	0-00%	6-02%	6-01%
<b>Total</b>		6-15%	1-03%	41-53%	0-00%	11-04%	59-12%
<b>Approved Violations</b>		34-85%	36-97%	37-47%	15-100%	295-96%	417-88%
<b>Total Notices Printed</b>		34-85%	36-97%	37-47%	15-100%	295-96%	417-88%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:39:05 AM

# Customer Management Report (San Mateo) All Detection Types

01-Dec-2014 to 31-Dec-2014

Operator Id: %

		SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
<b>Total Processed Incidents</b>		49	70	108	70	644	941
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	2	1	2	3	22	30
	Plate Obstruction	4	1	0	3	39	47
	Vehicle Obstruction	0	0	0	0	11	11
Police Rejects	Emergency Vehicle Responding	2	3	0	1	2	8
	Incorrect Plate on Vehicle	0	0	0	0	1	1
	Incorrect/Incomplete DMV	0	0	1	0	0	1
	Multiple vehicles in frame	0	0	0	0	13	13
	On or Passed the Stop Bar (PD).	1	9	43	6	269	328
	Plate Unidentifiable	0	2	0	0	1	3
	Slow Roll - right turn	0	0	1	0	10	11
	Sun Glare	0	0	0	0	1	1
	Weather Conditions	0	0	0	1	0	1
	Policy/Weather	Sun Glare	1	3	0	6	1
	Weather/Nature	0	0	0	1	3	4
Registration Issues	Paper Plates	0	1	2	2	17	22
<b>Total</b>		10	20	49	23	390	492
<b>Sub Total Violations</b>		39	50	59	47	254	449
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		39	50	59	47	254	449
<b>Less Rejects</b>							
Camera Malfunction	Face Not in Frame	1-03%	0-00%	0-00%	0-00%	0-00%	1-00%
	Image Missing	0-00%	0-00%	1-02%	0-00%	0-00%	1-00%
	Misc Camera Issue	6-15%	0-00%	8-14%	1-02%	1-00%	16-04%
Police Rejects	Driver Unidentifiable images poor	0-00%	1-02%	0-00%	0-00%	3-01%	4-01%
	Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	2-01%	2-00%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
<b>Total</b>		7-18%	1-02%	9-15%	1-02%	7-03%	25-06%
<b>Approved Violations</b>		32-82%	49-98%	50-85%	46-98%	247-97%	424-94%
<b>Total Notices Printed</b>		32-82%	49-98%	50-85%	46-98%	247-97%	424-94%

Generated By: MCARROLL

Generated On: 7/1/2015 11:39:36 AM

# Customer Management Report (San Mateo) All Detection Types

01-Dec-2014 to 31-Dec-2014

Operator Id: %

---

TOTAL	SAN-SAHI-01	SAN-HISA-01	SAN-HINO-03	SAN-HINO-01	SAN-4HU-01
-------	-------------	-------------	-------------	-------------	------------

---

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:39:36 AM

# Customer Management Report (San Mateo) All Detection Types

01-Jan-2015 to 31-Jan-2015

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL	
<b>Total Processed Incidents</b>	88	42	105	64	732	1031	
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	1	0	7	0	7	15
	Motor Cycle Helmet	0	0	1	0	0	1
	Plate Obstruction	0	4	1	1	14	20
	Vehicle Obstruction	2	3	5	2	22	34
Police Rejects	Emergency Vehicle Responding	3	0	0	2	4	9
	Multiple vehicles in frame	0	0	0	0	19	19
	On or Passed the Stop Bar (PD).	4	3	30	5	253	295
	Plate Unidentifiable	0	0	1	0	5	6
	Slow Roll - right turn	0	0	1	0	49	50
Policy/Weather	Extended Vehicle	0	0	2	1	0	3
	Sun Glare	3	2	0	4	7	16
Registration Issues	Paper Plates	3	1	3	3	24	34
<b>Total</b>		16	13	51	18	404	502
<b>Sub Total Violations</b>		72	29	54	46	328	529
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		72	29	54	46	328	529
<b>Less Rejects</b>							
Camera Malfunction	Rear Plate Camera Blurry	0-00%	1-03%	0-00%	0-00%	0-00%	1-00%
Police Rejects	Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Insufficient Strobe Lighting	0-00%	0-00%	1-02%	0-00%	6-02%	7-01%
Process Issues	Too Old	1-01%	0-00%	0-00%	0-00%	9-03%	10-02%
<b>Total</b>		1-01%	1-03%	1-02%	0-00%	16-05%	19-04%
<b>Approved Violations</b>		71-99%	28-97%	53-98%	46-100%	312-95%	510-96%
<b>Total Notices Printed</b>		71-99%	28-97%	53-98%	46-100%	312-95%	510-96%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:40:02 AM



# Customer Management Report (San Mateo) All Detection Types

01-Feb-2015 to 28-Feb-2015

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL	
<b>Total Processed Incidents</b>	93	52	90	36	705	976	
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	2	1	3	1	14	21
	Motor Cycle Helmet	3	0	0	0	1	4
	Plate Obstruction	0	2	1	0	4	7
	Vehicle Obstruction	3	1	3	0	28	35
Police Rejects	Emergency Vehicle Responding	3	2	0	1	8	14
	Multiple vehicles in frame	0	0	0	1	14	15
	On or Passed the Stop Bar (PD).	1	2	31	6	246	286
	Plate Obstruction (PD)	0	0	0	0	5	5
	Plate Unidentifiable	0	0	0	0	5	5
	Slow Roll - right turn	0	0	2	0	49	51
	Yielding to an Emergency	1	0	0	0	0	1
Policy/Weather	Extended Vehicle	0	0	0	1	0	1
	Sun Glare	5	0	1	5	4	15
	Weather/Nature	0	1	0	0	0	1
Registration Issues	Paper Plates	6	2	0	0	19	27
	Wrong or No DMV	0	0	0	0	1	1
<b>Total</b>		24	11	41	15	398	489
<b>Sub Total Violations</b>		69	41	49	21	307	487
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		69	41	49	21	307	487
<b>Less Rejects</b>							
Camera Malfunction	Misc Camera Issue	0-00%	0-00%	0-00%	1-05%	1-00%	2-00%
	Rear Plate Camera Blurry	0-00%	6-15%	0-00%	0-00%	0-00%	6-01%
Police Rejects Process Issues	Insufficient Strobe Lighting	1-01%	0-00%	1-02%	0-00%	10-03%	12-02%
	Too Old	1-01%	0-00%	3-06%	1-05%	16-05%	21-04%
<b>Total</b>		2-03%	6-15%	4-08%	2-10%	27-09%	41-08%
<b>Approved Violations</b>		67-97%	35-85%	45-92%	19-90%	280-91%	446-92%
<b>Total Notices Printed</b>		67-97%	35-85%	45-92%	19-90%	280-91%	446-92%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:40:30 AM

# Customer Management Report (San Mateo) All Detection Types

01-Mar-2015 to 31-Mar-2015

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL	
<b>Total Processed Incidents</b>	115	80	112	57	850	1214	
<b>Less Uncontrollable Factors</b>							
Obstruction	Driver Obstruction/Duckers	4	0	3	0	4	11
	Plate Obstruction	1	2	1	2	6	12
	Vehicle Obstruction	3	2	5	1	40	51
Police Rejects	Emergency Vehicle Responding	4	2	3	0	2	11
	Incorrect Plate on Vehicle	0	0	0	0	1	1
	Incorrect/Incomplete DMV	0	0	1	1	1	3
	Multiple vehicles in frame	0	0	1	1	14	16
	On or Passed the Stop Bar (PD).	4	14	23	9	283	333
	Plate Obstruction (PD)	1	0	0	0	0	1
	Plate Unidentifiable	1	0	1	0	0	2
	Slow Roll - right turn	0	0	0	0	37	37
Policy/Weather	Extended Vehicle	3	0	0	0	0	3
	Sun Glare	8	3	2	5	3	21
Registration Issues	Paper Plates	3	1	4	3	27	38
<b>Total</b>		32	24	44	22	418	540
<b>Sub Total Violations</b>		83	56	68	35	432	674
Less in Progress		0	0	0	0	0	0
<b>Available For Prosecution</b>		83	56	68	35	432	674
<b>Less Rejects</b>							
Camera Malfunction	Face Camera Flash	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Face Not in Frame	5-06%	0-00%	0-00%	0-00%	1-00%	6-01%
	Plate Not in Frame	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
	Rear Plate Camera Blurry	0-00%	4-07%	0-00%	0-00%	3-01%	7-01%
Police Rejects	Driver Unidentifiable images poor	2-02%	0-00%	0-00%	1-03%	1-00%	4-01%
	Insufficient Strobe Lighting	0-00%	0-00%	1-01%	0-00%	7-02%	8-01%
Process Issues	Too Old	6-07%	6-11%	14-21%	7-20%	132-31%	165-24%
<b>Total</b>		13-16%	10-18%	15-22%	8-23%	146-34%	192-28%
<b>Approved Violations</b>		70-84%	46-82%	53-78%	27-77%	286-66%	482-72%
<b>Total Notices Printed</b>		70-84%	46-82%	53-78%	27-77%	286-66%	482-72%

Generated By: MCARROLL

Generated On: 7/1/2015 11:41:03 AM

# Customer Management Report (San Mateo) All Detection Types

01-Mar-2015 to 31-Mar-2015

Operator Id: %

---

TOTAL	SAN-SAHI-01	SAN-HISA-01	SAN-HINO-03	SAN-HINO-01	SAN-4HU-01
-------	-------------	-------------	-------------	-------------	------------

---

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:41:03 AM

# Customer Management Report (San Mateo) All Detection Types

01-Apr-2015 to 30-Apr-2015

Operator Id: %

	SAN-4HU-01	SAN-HINO-01	SAN-HINO-03	SAN-HISA-01	SAN-SAHI-01	TOTAL
<b>Total Processed Incidents</b>	54	65	111	59	712	1001
<b>Less Uncontrollable Factors</b>						
Obstruction						
Driver Obstruction/Duckers	1	0	2	0	11	14
Motor Cycle Helmet	1	0	0	1	0	2
Plate Obstruction	1	1	0	0	12	14
Vehicle Obstruction	2	0	10	1	34	47
Police Rejects						
Emergency Vehicle Responding	2	1	0	0	4	7
Incorrect/Incomplete DMV	0	0	0	0	2	2
Multiple vehicles in frame	0	0	0	0	7	7
On or Passed the Stop Bar (PD).	1	10	26	11	240	288
Slow Roll - right turn	0	0	1	0	31	32
Policy/Weather						
Extended Vehicle	0	0	0	1	0	1
Sun Glare	7	2	5	6	35	55
Registration Issues						
Out of Country Plate	0	0	1	0	0	1
Paper Plates	0	1	1	1	22	25
Wrong or No DMV	0	0	0	0	1	1
<b>Total</b>	15	15	46	21	399	496
<b>Sub Total Violations</b>	39	50	65	38	313	505
Less in Progress	0	0	0	0	0	0
<b>Available For Prosecution</b>	39	50	65	38	313	505
<b>Less Rejects</b>						
Camera Malfunction						
Rear Plate Camera Blurry	0-00%	3-06%	0-00%	0-00%	3-01%	6-01%
Scene Image Flash Inappropriate	0-00%	0-00%	0-00%	0-00%	3-01%	3-01%
Police Rejects						
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Insufficient Strobe Lighting	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%
Process Issues						
Too Old	0-00%	0-00%	2-03%	1-03%	5-02%	8-02%
<b>Total</b>	0-00%	3-06%	2-03%	1-03%	13-04%	19-04%
<b>Approved Violations</b>	39-100%	47-94%	63-97%	37-97%	300-96%	486-96%
<b>Total Notices Printed</b>	39-100%	47-94%	63-97%	37-97%	299-96%	485-96%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Generated By: MCARROLL

Generated On: 7/1/2015 11:41:30 AM