

need 2.10.12 by US PS

Customer Management Report (Culver City) All Detection Types

01-Jan-2011 to 31-Jan-2011 Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL
Total Processed Incidents	65	151	180	168	129	282	248	451	209	113	249	100	191	133	65	87	108	207	3136
Less Uncontrollable Factors																			
Obstruction	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	2
Plate Obstruction																			
Police	0	4	1	1	1	7	10	8	3	5	3	1	2	1	1	1	1	2	52
Rejects	0	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2
Driver Obstruction - Duckers																			
Emergency Vehicle Responding	10	13	8	13	11	5	3	5	3	17	21	15	8	2	2	2	1	7	146
Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	97	0	0	0	0	0	0	0	97
Multiple vehicles in frame	0	1	0	0	0	4	1	6	1	1	0	1	0	0	0	0	0	0	15
No Plates	0	2	2	1	0	0	1	2	2	1	1	0	2	2	0	1	0	2	19
On or Passed the Stop Bar (PD)	4	1	0	2	4	13	2	17	1	1	1	2	5	12	4	1	0	0	70
Plate Unidentifiable	3	3	5	3	1	13	2	13	8	1	4	5	6	5	2	1	3	38	116
Police Discretion	12	12	13	19	23	9	89	38	14	3	20	4	10	6	9	4	2	47	334
Straight Thru On Left	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1
Vehicle Obstruction	0	1	1	0	2	9	1	2	2	1	0	1	1	0	0	1	1	0	23
Yielding to an Emergency	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Policy/Weath	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Sun Glare																			
Total	30	37	31	39	42	61	109	94	34	30	147	29	34	28	18	11	8	97	879
Sub Total Violations	35	114	149	129	87	221	139	357	175	83	102	71	157	105	47	76	100	110	2257
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	35	114	149	129	87	221	139	357	175	83	102	71	157	105	47	76	100	110	2257
Less Rejects	4-11%	12-11%	5-03%	5-04%	17-20%	18-08%	41-29%	36-10%	21-12%	10-12%	7-07%	7-10%	5-03%	3-03%	6-13%	5-07%	0-00%	15-14%	217-10%
Police	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Unclear	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Customer Management Report (Culver City) All Detection Types

01-Jan-2011 to 31-Jan-2011

Operator Id: %

Category	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL
Unclear Scene Image	1-03% 5-14%	2-02% 15-13%	2-01% 7-05%	0-00% 5-04%	2-02% 19-22%	18-08% 36-16%	3-02% 44-32%	13-04% 49-14%	17-10% 38-22%	7-08% 17-20%	4-04% 11-11%	1-01% 8-11%	1-01% 6-04%	2-02% 5-05%	1-02% 7-15%	0-00% 5-07%	1-01% 1-01%	11-10% 27-25%	86-04% 305-14%
Approved Violations	30-86%	99-87%	142-95%	124-96%	68-78%	185-84%	95-58%	308-86%	137-78%	66-80%	91-89%	63-59%	151-96%	100-95%	40-85%	71-93%	99-99%	83-75%	1952-86%
Total Notices Printed	30-86%	99-87%	142-95%	124-96%	68-78%	185-84%	95-58%	308-86%	137-78%	66-80%	91-89%	63-59%	151-96%	100-95%	40-85%	71-93%	99-99%	83-75%	1952-86%

Customer Management Report (Culver City) Redlight Incidents

01-Apr-2011 to 30-Apr-2011

Operator Id: %

	59	315	112	108	38	67	239	207	273	72	134	63	126	75	19	11	119	100	2137
	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL
Total Processed Incidents	1	8	2	2	0	2	4	3	7	0	0	0	0	0	1	0	0	2	32
Less Uncontrollable Factors																			
Police Driver Obstruction (PD)	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Rejects Driver Obstruction - Duckers	27	16	7	12	3	3	2	3	9	6	19	14	10	2	2	1	0	5	141
Emergency Vehicle Responding	0	0	0	0	0	0	0	3	0	0	29	0	0	0	0	0	0	0	32
Funeral Procession/Police	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Incorrect Plate on Vehicle	0	3	0	0	0	0	0	3	6	0	0	0	1	0	0	0	0	0	14
Multiple vehicles in frame	0	0	0	1	0	2	0	0	0	0	1	0	1	0	0	0	0	0	5
No Plates	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Non Violation - Green Light	5	2	0	0	0	1	5	6	2	1	0	3	0	7	1	0	1	1	35
On or Passed the Stop Bar (PD)	1	14	8	4	0	3	3	3	5	0	4	0	5	0	2	0	0	8	60
Plate Unidentifiable	9	34	8	19	10	5	161	31	16	0	17	3	7	3	4	3	1	40	371
Police Discretion	0	0	2	0	0	2	0	0	15	1	0	0	0	0	0	0	0	0	20
Straight Thru On Left	0	16	1	0	0	2	1	5	14	4	0	1	3	1	0	0	8	0	56
Vehicle Obstruction	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Registration Paper Plates	43	94	28	39	13	20	176	58	74	12	70	21	26	14	10	4	10	58	770
Issues	16	221	84	69	25	47	63	149	199	60	64	42	100	61	9	7	109	42	1367
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	16	221	84	69	25	47	63	149	199	60	64	42	100	61	9	7	109	42	1367
Available For Prosecution																			
Less Rejects																			
Camera Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Malfunction Driver Unidentifiable images poor	1-06%	11-05%	2-02%	5-07%	2-08%	3-06%	1-02%	4-03%	19-09%	4-07%	10-16%	5-12%	2-02%	2-03%	1-11%	1-14%	1-01%	5-12%	76-06%
Police Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rejects Equipment Malfunction																			

Generated By: OCORRALES
Generated On: 2/6/2012 12:10:17 PM

© Redflex Traffic Systems, Inc.

Customer Management Report (Culver City) Redlight Incidents

01-Apr-2011 to 30-Apr-2011

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL
No Images	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Sun Glare	1-06%	6-03%	0-00%	0-00%	1-04%	2-04%	0-00%	5-04%	13-07%	0-00%	6-09%	0-00%	2-02%	2-03%	0-00%	0-00%	1-01%	2-05%	42-03%
Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Total	2-12%	17-08%	2-02%	5-07%	3-12%	6-13%	1-02%	12-08%	31-16%	4-07%	16-25%	5-12%	5-05%	4-07%	1-11%	1-14%	2-02%	7-17%	124-09%
Approved Violations	14-88%	204-92%	82-98%	64-93%	22-88%	41-87%	62-98%	137-92%	168-84%	56-93%	48-75%	37-88%	95-95%	57-93%	8-89%	6-86%	107-98%	35-83%	1243-91%
Total Notices Printed	14-88%	204-92%	82-98%	64-93%	22-88%	41-87%	62-98%	137-92%	168-84%	56-93%	48-75%	37-88%	95-95%	57-93%	8-89%	6-86%	107-98%	35-83%	1243-91%

Customer Management Report (Culver City) Redlight Incidents

01-Jun-2011 to 30-Jun-2011

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL
Total Processed Incidents	62	230	101	104	35	45	0	0	0	0	217	77	146	83	14	17	117	107	1355
Less Uncontrollable Factors																			
Obstruction	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Police	0	5	1	2	1	0	0	0	0	0	1	1	1	2	0	0	0	2	16
Driver Obstruction (PD)	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Driver Obstruction - Duckers	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Emergency Vehicle Responding	26	19	12	9	5	2	0	0	0	0	24	25	8	4	2	1	1	3	141
Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	48	0	0	0	0	0	0	0	48
Multiple vehicles in frame	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
No Plates	0	1	2	0	0	0	0	0	0	0	2	0	1	0	0	0	0	0	6
On or Passed the Stop Bar (PD)	5	3	0	1	1	0	0	0	0	0	3	0	3	7	1	0	1	0	25
Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Plate Unidentifiable	1	5	2	3	0	0	0	0	0	0	7	1	1	3	1	0	1	8	33
Police Discretion	16	44	7	21	10	9	0	0	0	0	43	3	21	2	5	3	0	48	232
Straight Thru On Left	0	0	1	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	3
Vehicle Obstruction	0	3	0	0	0	2	0	0	0	0	3	2	4	1	0	0	3	0	18
Registration	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Paper Plates	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Issues	48	82	25	36	18	15	0	0	0	0	131	32	39	20	9	4	11	61	531
Sub Total Violations	14	148	76	68	17	30	0	0	0	0	86	45	107	63	5	13	106	46	824
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	14	148	76	68	17	30	0	0	0	0	86	45	107	63	5	13	106	46	824
Less Rejects																			
Police	0-00%	7-05%	3-04%	5-07%	2-12%	0-00%	0-00%	0-00%	0-00%	0-00%	13-15%	9-20%	1-01%	4-86%	0-00%	1-08%	4-04%	3-07%	52-06%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
No Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: OCORRALES

Generated On: 2/6/2012 12:11:17 PM

© Redflex Traffic Systems, Inc.

Customer Management Report (Culver City) Redlight Incidents

01-Jun-2011 to 30-Jun-2011

Operator Id: %

Category	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL
Total	0.00% 0-00%	6.04% 13-09%	0.00% 3-04%	2.03% 7-10%	0.00% 2-12%	2.07% 2-07%	0.00% 0-00%	0.00% 0-00%	0.00% 0-00%	0.00% 0-00%	6.07% 19-22%	1.02% 10-22%	13.12% 15-14%	4.06% 8-13%	0.00% 0-00%	1.98% 2-15%	5.05% 9-08%	2.04% 5-11%	42.05% 95-12%
Approved Violations	14-100%	135-91%	73-96%	61-80%	15-88%	28-93%	0-00%	0-00%	0-00%	0-00%	67-78%	35-78%	92-86%	55-87%	5-100%	11-85%	97-82%	41-89%	729-88%
Total Notices Printed	14-100%	135-91%	73-96%	61-80%	15-88%	28-93%	0-00%	0-00%	0-00%	0-00%	67-78%	35-78%	92-86%	55-87%	5-100%	11-85%	97-82%	41-89%	729-88%

Customer Management Report (Culver City) Redlight Incidents

Operator Id: %

01-Jul-2011 to 31-Jul-2011

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL
Total Processed Incidents	52	278	127	143	39	26	0	0	0	0	198	76	162	100	12	13	118	124	1468
Less Uncontrollable Factors																			
Police	0	6	0	0	0	1	0	0	0	0	0	0	2	0	0	0	1	1	11
Rejects	20	29	6	9	5	2	0	0	0	0	29	15	10	6	2	0	0	4	137
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	38	0	0	0	0	0	0	0	38
Funeral Procession/Police	0	2	1	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	5
Multiple vehicles in frame	0	1	1	0	0	0	0	0	0	0	0	0	1	1	0	0	1	0	5
No Plates	0	0	0	1	1	0	0	0	0	0	0	0	1	1	0	0	1	0	5
On or Passed the Stop Bar (PD)	0	0	0	1	1	0	0	0	0	0	1	0	0	11	1	0	2	0	17
Plate Unidentifiable	0	2	3	4	0	1	0	0	0	0	7	2	3	4	1	0	1	12	40
Police Discretion	17	67	4	30	6	6	0	0	0	0	22	4	25	2	3	2	2	67	257
Straight Thru On Left	0	0	3	0	1	0	0	0	0	0	0	2	0	0	0	0	0	0	6
Vehicle Obstruction	0	4	3	0	0	1	0	0	0	0	0	0	1	2	0	0	0	0	11
Total	37	111	21	45	13	11	0	0	0	0	97	23	42	26	7	2	8	84	527
Sub Total Violations	15	167	106	98	26	15	0	0	0	0	101	53	120	74	5	11	110	40	941
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	15	167	106	98	26	15	0	0	0	0	101	53	120	74	5	11	110	40	941
Less Rejects																			
Police	2-13%	8-05%	3-03%	9-09%	1-04%	1-07%	0-00%	0-00%	0-00%	0-00%	5-05%	5-09%	3-02%	4-05%	0-00%	2-18%	7-05%	2-05%	52-06%
Rejects	0-00%	11-07%	0-00%	2-02%	0-00%	1-07%	0-00%	0-00%	0-00%	0-00%	8-08%	0-00%	7-06%	7-09%	0-00%	1-09%	3-03%	4-10%	44-05%
Total	2-13%	19-11%	3-03%	11-11%	1-04%	2-13%	0-00%	0-00%	0-00%	0-00%	13-13%	5-09%	10-08%	11-15%	0-00%	3-27%	10-09%	6-15%	95-10%
Approved Violations	13-87%	146-89%	103-87%	87-89%	25-96%	13-87%	0-00%	0-00%	0-00%	0-00%	86-87%	48-91%	110-92%	63-85%	5-100%	8-73%	100-91%	34-85%	845-90%
Total Notices Printed	13-87%	146-89%	103-87%	87-89%	25-96%	13-87%	0-00%	0-00%	0-00%	0-00%	86-87%	48-91%	110-92%	63-85%	5-100%	8-73%	100-91%	34-85%	845-90%

Customer Management Report (Culver City) Redlight Incidents

01-Aug-2011 to 31-Aug-2011

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL	
Total Processed Incidents	57	297	105	204	32	35	0	0	0	0	198	71	138	117	26	26	156	85	1547	
Less Uncontrollable Factors	0	2	0	1	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	4
Obstruction	0	5	1	4	2	1	0	0	0	0	3	0	1	0	0	0	0	0	0	17
Plate Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Driver Obstruction (PD)	23	23	9	10	1	2	0	0	0	25	54	10	8	6	7	2	3	6	135	
Driver Obstruction - Duckers	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	54	
Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Multiple vehicles in frame	0	1	3	0	0	0	0	0	0	0	0	1	0	0	0	0	2	0	7	
No Plates	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	1	0	0	3	
On or Passed the Stop Bar (PD)	1	1	2	2	0	0	0	0	0	2	2	3	0	9	1	1	4	0	26	
Plate Unidentifiable	3	9	2	6	0	2	0	0	0	8	8	8	2	4	1	0	0	10	55	
Police Discretion	17	56	6	43	6	10	0	0	0	23	0	25	2	2	4	8	4	33	237	
Vehicle Obstruction	1	0	0	0	0	2	0	0	0	1	4	3	1	0	0	0	3	2	17	
Registration Issues	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
Total	45	98	23	66	11	17	0	0	0	116	28	40	22	13	12	16	51	558		
Sub Total Violations	12	199	82	138	21	18	0	0	0	82	43	98	95	13	14	140	34	989		
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	12	199	82	138	21	18	0	0	0	82	43	98	95	13	14	140	34	989		
Less Rejects	0-00%	8-04%	0-00%	1-01%	2-10%	1-06%	0-00%	0-00%	0-00%	0-00%	5-06%	3-07%	4-04%	5-05%	0-00%	3-21%	7-05%	1-03%	40-04%	
Police	0-00%	13-07%	1-01%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	5-06%	0-00%	0-00%	0-00%	0-00%	1-07%	3-02%	2-06%	25-03%	
Rejects	0-00%	21-11%	1-01%	4-03%	2-10%	1-06%	0-00%	0-00%	0-00%	10-12%	3-07%	4-04%	5-05%	0-00%	4-23%	10-07%	3-09%	66-07%		
Total	12-100%	178-88%	81-99%	134-97%	19-90%	17-94%	0-00%	0-00%	0-00%	72-88%	40-93%	94-96%	90-95%	13-100%	10-71%	130-83%	31-91%	921-83%		
Approved Violations																				

Generated By: OCORRALES

Generated On: 2/6/2012 12:12:30 PM

© Reflex Traffic Systems, Inc.

Customer Management Report (Culver City) Redlight Incidents

01-Aug-2011 to 31-Aug-2011

Operator Id: %

TOTAL	921-93%
CC-WASA-01	31-91%
CC-WAHE-03	130-93%
CC-WAHE-01	10-71%
CC-WACE-01	13-100%
CC-WABE-03	90-95%
CC-WABE-01	94-96%
CC-SLBU-03	40-83%
CC-SLBU-01	72-88%
CC-SESL-03	0-00%
CC-SESL-01	0-00%
CC-SEGV-03	0-00%
CC-SEGV-01	0-00%
CC-JEOV-03	17-84%
CC-JEDU-03	19-80%
CC-JEDU-01	134-97%
CC-JECO-01	81-89%
CC-CIWA-01	178-89%
CC-CEWA-01	12-100%

Total Notices Printed

Customer Management Report (Culver City) Redlight Incidents

01-Sep-2011 to 30-Sep-2011 Operator Id: %

	80	257	111	178	35	40	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL	
Total Processed Incidents	80	257	111	178	35	40	0	0	0	0	207	90	112	67	16	22	104	75	1394	
Less Uncontrollable Factors																				
Police	0	2	3	2	0	4	0	0	0	0	1	3	0	0	0	0	0	1	16	
Rejects	32	28	7	14	4	0	0	0	0	0	17	16	4	1	1	1	1	2	128	
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Emergency Vehicle Responding	0	0	0	0	0	0	0	0	0	0	51	0	0	0	0	0	0	0	51	
Funeral Procession/Police	0	1	0	1	0	1	0	0	0	0	0	1	0	0	0	0	0	0	5	
Multiple vehicles in frame	0	2	0	0	0	0	0	0	0	0	0	1	1	0	0	0	0	1	5	
No Plates	1	2	3	3	2	0	0	0	0	0	6	1	1	1	0	0	2	1	23	
On or Passed the Stop Bar (PD)	3	5	0	0	1	1	0	0	0	0	4	3	0	1	1	0	1	8	28	
Plate Unidentifiable	24	54	7	36	8	7	0	0	0	0	32	10	22	3	1	6	1	34	245	
Police Discretion	0	5	0	0	0	2	0	0	0	0	2	6	0	1	0	0	1	1	18	
Vehicle Obstruction	60	99	20	56	15	15	0	0	0	0	113	41	27	7	3	8	7	48	519	
Sub Total Violations	20	158	91	122	20	25	0	0	0	0	94	49	85	60	13	14	97	27	875	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	20	158	91	122	20	25	0	0	0	0	94	49	85	60	13	14	97	27	875	
Less Rejects																				
Police	0-00%	4-03%	2-02%	3-02%	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	3-03%	4-08%	1-01%	0-00%	1-08%	1-07%	2-02%	2-07%	25-03%	
Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
Driver Unidentifiable images poor	1-05%	11-07%	1-01%	0-00%	1-05%	2-08%	0-00%	0-00%	0-00%	0-00%	6-05%	0-00%	2-07%	2-03%	1-05%	0-00%	1-01%	1-04%	28-03%	
No Images	1-05%	15-09%	3-03%	3-02%	1-55%	4-16%	0-00%	0-00%	0-00%	0-00%	9-10%	4-08%	4-05%	2-03%	2-15%	1-07%	3-03%	3-11%	55-06%	
Sun Glare	19-95%	143-91%	88-97%	119-98%	19-95%	21-84%	0-00%	0-00%	0-00%	0-00%	85-90%	45-92%	81-95%	58-97%	11-85%	13-83%	94-97%	24-89%	820-94%	
Approved Violations	19-95%	143-91%	88-97%	119-98%	19-95%	21-84%	0-00%	0-00%	0-00%	0-00%	85-90%	45-92%	81-95%	58-97%	11-85%	13-83%	94-97%	24-89%	820-94%	
Total Notices Printed	19-95%	143-91%	88-97%	119-98%	19-95%	21-84%	0-00%	0-00%	0-00%	0-00%	85-90%	45-92%	81-95%	58-97%	11-85%	13-83%	94-97%	24-89%	820-94%	

Customer Management Report (Culver City) Redlight Incidents

01-Oct-2011 to 31-Oct-2011

Operator Id: %

	57	279	140	202	35	55	0	0	0	0	2192	113	166	122	84	31	159	112	TOTAL	
	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01		
Total Processed Incidents	57	279	140	202	35	55	0	0	0	0	2192	113	166	122	84	31	159	112	3747	
Less Uncontrollable Factors																				
Police	1	9	2	4	1	3	0	0	0	0	2	3	1	0	0	0	2	0	28	
Rejects	16	22	6	10	4	3	0	0	0	0	17	8	10	8	4	3	0	5	116	
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	26	0	0	0	0	0	0	0	26	
Emergency Vehicle Responding	0	2	3	0	0	0	0	0	0	0	1	0	0	0	0	0	2	0	8	
Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Multiple vehicles in frame	0	0	1	1	0	0	0	0	0	0	1	0	1	0	0	0	0	1	6	
No Plates	1	0	1	2	2	1	0	0	0	0	4	0	0	3	0	1	1	1	17	
On or Passed the Stop Bar (PD)	2	4	3	0	0	0	0	0	0	0	8	2	5	2	6	0	0	8	40	
Plate Unidentifiable	16	62	8	56	6	7	0	0	0	0	27	5	23	6	48	4	5	55	328	
Police Discretion	0	0	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3	
Straight Thru On Left	0	5	0	1	0	2	0	0	0	0	1	2	1	6	0	0	2	1	21	
Vehicle Obstruction	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	0	2	
Registration Paper Plates	36	104	27	75	13	16	0	0	0	0	87	20	41	25	58	8	13	71	594	
Sub Total Violations	21	175	113	127	22	39	0	0	0	0	2105	93	125	97	26	23	146	41	3153	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	21	175	113	127	22	39	0	0	0	0	2105	93	125	97	26	23	146	41	3153	
Less Rejects																				
Police	0-00%	9-05%	0-00%	2-02%	2-09%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%	2-02%	3-02%	1-01%	2-08%	2-09%	1-01%	2-05%	29-01%	
Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%	
Driver Unidentifiable images poor	1-05%	0-00%	0-00%	0-00%	0-00%	1-03%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-01%	0-00%	1-04%	0-00%	0-00%	5-00%	
No Video	1-05%	9-05%	0-00%	2-02%	2-09%	1-03%	0-00%	0-00%	0-00%	0-00%	8-00%	2-02%	3-02%	2-08%	3-13%	1-01%	2-05%	2-05%	38-01%	
Sun Glare	20-95%	166-95%	113-100%	125-98%	20-81%	38-97%	0-00%	0-00%	0-00%	0-00%	2097-100%	91-98%	122-98%	95-98%	24-92%	20-87%	145-98%	39-95%	3115-99%	
Approved Violations	20-95%	166-95%	113-100%	125-98%	20-81%	38-97%	0-00%	0-00%	0-00%	0-00%	2097-100%	91-98%	122-98%	95-98%	24-92%	20-87%	145-98%	39-95%	3115-99%	
Total Notices Printed	20-95%	166-95%	113-100%	125-98%	20-81%	38-97%	0-00%	0-00%	0-00%	0-00%	2097-100%	91-98%	122-98%	95-98%	24-92%	20-87%	145-98%	39-95%	3115-99%	

Generated By: OCORRALES
Generated On: 2/6/2012 12:13:34 PM

© Reflex Traffic Systems, Inc.

Customer Management Report (Culver City) Redlight Incidents

01-Nov-2011 to 30-Nov-2011

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL
Total Processed Incidents	54	183	127	201	45	55	0	0	0	0	200	91	148	123	121	16	133	104	1601
Less Uncontrollable Factors																			
Obstruction Plate Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
Police Driver Obstruction (PD)	0	6	0	1	1	3	0	0	0	0	1	2	2	1	1	0	1	0	19
Rejects Emergency Vehicle Responding	16	31	4	13	2	1	0	0	0	0	26	7	12	3	3	1	4	5	128
Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	52	0	0	0	0	0	0	0	52
Multiple vehicles in frame	0	1	0	0	0	1	0	0	0	0	0	1	0	0	0	0	0	0	3
No Plates	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	2	3
On or Passed the Stop Bar (PD)	1	1	1	1	0	1	0	0	0	0	0	0	1	3	0	1	1	0	11
Plate Unidentifiable	1	3	0	6	0	1	0	0	0	0	3	4	1	1	9	0	0	3	32
Police Discretion	21	33	6	54	18	10	0	0	0	0	28	6	15	6	69	1	3	59	329
Straight Thru On Left	0	16	0	0	0	1	0	0	0	0	3	3	0	0	0	0	0	0	23
Vehicle Obstruction	0	1	8	1	0	3	0	0	0	0	2	3	4	6	0	0	1	1	30
Total	39	76	35	76	21	21	0	0	0	0	115	29	36	21	82	3	10	70	633
Sub Total Violations	15	107	92	125	24	34	0	0	0	0	85	65	112	102	39	13	123	34	970
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	15	107	92	125	24	34	0	0	0	0	85	65	112	102	39	13	123	34	970
Less Rejects																			
Police Driver Unidentifiable images poor	1-07%	4-04%	1-01%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	7-08%	2-03%	0-00%	2-02%	2-05%	0-00%	0-00%	2-06%	23-02%
Rejects Sun Glare	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	2-06%	6-01%
Total	1-07%	6-06%	1-01%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	8-03%	2-03%	0-00%	2-02%	2-05%	0-00%	1-01%	4-12%	29-03%
Approved Violations	14-93%	101-94%	91-99%	123-98%	24-100%	34-100%	0-00%	0-00%	0-00%	0-00%	77-91%	63-97%	112-100%	100-98%	37-95%	13-100%	122-99%	30-88%	941-97%
Total Notices Printed	14-93%	101-94%	91-99%	123-98%	24-100%	34-100%	0-00%	0-00%	0-00%	0-00%	77-91%	63-97%	112-100%	100-98%	37-95%	13-100%	122-99%	30-88%	941-97%

Customer Management Report (Culver City) Redlight Incidents

01-Dec-2011 to 31-Dec-2011

Operator Id: %

	77	180	190	169	39	112	52	49	71	39	197	75	177	126	114	16	97	108	1888
	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-03	CC-WASA-01	TOTAL	
Total Processed Incidents	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Less Uncontrollable Factors	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Obstruction - Plate Obstruction	1	5	2	1	0	2	0	0	0	0	0	0	3	0	0	0	2	1	17
Police Rejects	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	2
Driver Obstruction - Duckers	27	28	4	13	1	0	2	4	1	6	23	17	11	4	9	0	0	7	157
Emergency Vehicle Responding	0	0	0	0	0	0	0	3	0	0	38	0	0	0	0	0	0	0	41
Funeral Procession/Police	0	1	2	0	0	1	0	0	0	0	2	0	0	0	0	0	0	0	7
Multiple vehicles in frame	0	2	0	0	0	1	0	0	0	0	0	1	1	0	0	0	0	0	5
No Plates	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1
Non Violation - Green Light	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	1
On or Passed the Stop Bar (PD)	0	3	2	1	2	1	16	15	0	0	2	2	1	2	6	0	1	4	58
Plate Obstruction (PD)	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Plate Unidentifiable	1	1	7	3	0	8	2	1	2	0	7	2	2	1	4	0	1	4	46
Police Discretion	18	35	10	52	8	8	9	3	2	1	23	5	14	2	68	4	2	54	318
Straight Thru On Left	0	1	17	0	0	6	0	0	0	10	11	5	1	0	0	0	0	0	51
Vehicle Obstruction	1	6	10	0	0	12	0	0	4	4	5	2	7	0	1	0	1	1	54
Policy/Weather	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
er	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Total	48	82	54	71	12	40	29	26	9	23	111	34	41	9	88	4	8	71	760
Sub Total Violations	29	98	136	98	27	72	23	23	62	16	86	41	136	117	26	12	89	37	1128
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	29	98	136	98	27	72	23	23	62	16	86	41	136	117	26	12	89	37	1128
Less Rejects	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Camera Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%

Generated By: OCORRALES
Generated On: 2/6/2012 12:14:27 PM

© Redflex Traffic Systems, Inc.

Customer Management Report (Culver City) Redlight Incidents

01-Dec-2011 to 31-Dec-2011

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL
Police Rejects	0-00%	1-01%	1-01%	1-01%	2-07%	2-03%	0-00%	0-00%	5-08%	2-12%	5-06%	1-02%	1-01%	4-03%	0-00%	0-00%	0-00%	2-05%	27-02%
Driver Unidentifiable images poor	1-03%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
No Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Unclear	1-03%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	6-01%
Sun Glare	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	2-07%	1-01%	2-01%	2-02%	2-07%	3-04%	0-00%	0-00%	6-10%	2-12%	7-08%	2-05%	1-01%	4-03%	0-00%	0-00%	2-02%	2-05%	38-03%
Approved Violations	27-83%	97-99%	134-99%	96-98%	25-93%	69-96%	23-100%	23-100%	56-90%	14-88%	79-92%	39-95%	135-99%	113-97%	26-100%	12-100%	87-98%	35-95%	1090-97%
Total Notices Printed	27-83%	97-99%	134-99%	96-98%	25-93%	69-96%	23-100%	23-100%	56-90%	14-88%	79-92%	39-95%	135-99%	113-97%	26-100%	12-100%	87-98%	35-95%	1090-97%

Customer Management Report (Culver City) Redlight Incidents

01-Jan-2011 to 31-Dec-2011
Operator Id: %

	766	2736	1541	1835	588	1022	1094	1291	1366	518	4282	948	1754	1219	534	403	1386	1356	24639
	TOTAL																		
Total Processed Incidents	766	2736	1541	1835	588	1022	1094	1291	1366	518	4282	948	1754	1219	534	403	1386	1356	24639
Less Uncontrollable Factors																			
Obstruction	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Driver Obstruction/Duckers	1	2	0	2	0	1	0	0	0	0	0	2	0	1	0	1	0	0	0
Plate Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Driver ID - Poor Driver Image -	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Driver Obstruction (PD)	3	64	17	17	7	35	22	25	34	16	22	11	13	6	6	1	9	11	319
Driver Obstruction - Duckers	0	0	1	0	1	0	0	2	0	3	0	0	1	0	0	0	0	0	0
Emergency Vehicle Responding	264	268	86	134	50	21	16	18	35	42	255	172	104	48	36	13	13	57	1632
Funeral Procession/Police	0	0	0	0	0	0	0	12	0	0	542	0	0	0	0	0	0	0	554
Incorrect Plate on Vehicle	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0
Multiple vehicles in frame	0	18	12	3	0	9	3	13	22	8	3	5	2	3	0	0	12	1	114
No Plates	1	14	6	4	1	7	1	4	9	1	10	3	9	4	0	3	2	8	87
Non Violation - Green Light	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
On or Passed the Stop Bar (PD)	25	19	12	16	20	29	23	55	15	3	24	24	27	83	18	5	16	9	423
Plate Obstruction (PD)	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Plate Unidentifiable	17	56	43	35	3	45	11	30	24	5	69	35	43	29	33	3	11	135	627
Police Discretion	196	476	88	389	128	98	599	130	74	19	313	52	200	45	224	124	27	553	3735
Straight Thru On Left	0	1	44	0	1	13	0	0	25	13	15	10	1	0	0	0	0	0	124
Vehicle Obstruction	3	46	30	3	3	52	3	11	60	24	18	25	28	24	1	3	23	10	367
Yielding to an Emergency	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0
Policy/Weather	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Extended Vehicle	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sun Glare	0	0	0	0	0	1	0	1	0	0	0	0	0	0	0	0	0	0	0

Generated By: OCORRALES
Generated On: 2/6/2012 12:15:00 PM

© Redflex Traffic Systems, Inc.

Customer Management Report (Culver City) Redlight Incidents

01-Jan-2011 to 31-Dec-2011

Operator Id: %

	CC-CIWA-01	CC-JECC-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	CC-WACE-01	CC-WAHE-01	CC-WAHE-03	CC-WASA-01	TOTAL
Registration	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Out of County Plate	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Issues	968	339	605	216	311	679	302	299	134	1271	340	431	244	318	153	115	788	8023
Paper Plates	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	256	1768	1202	372	711	415	889	1067	384	3011	608	1323	975	216	250	1271	568	16616
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	256	1768	1202	372	711	415	889	1067	384	3011	608	1323	975	216	250	1271	568	16616
Less Rejects																		
Camera	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Misc Camera Issue	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Rear Plate Camera Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Police	13-05%	82-05%	29-02%	34-09%	39-05%	63-15%	69-07%	102-10%	30-08%	76-03%	50-08%	28-02%	32-03%	16-07%	18-07%	29-02%	55-10%	810-05%
Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Equipment Malfunction	1-00%	0-00%	1-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
No Images	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
No Video	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Plate Unclear	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Sun Glare	6-02%	53-03%	2-00%	2-01%	9-01%	1-00%	7-01%	31-03%	0-00%	51-02%	2-00%	30-02%	18-02%	1-00%	5-02%	19-01%	20-04%	265-02%
Unclear Scene Image	2-01%	2-00%	3-00%	3-01%	26-04%	4-01%	17-02%	26-02%	12-03%	9-00%	2-00%	1-00%	2-00%	1-00%	7-03%	1-00%	11-02%	130-01%
Total	22-09%	135-08%	35-03%	39-10%	76-11%	66-16%	95-10%	159-15%	42-11%	140-05%	55-09%	62-05%	53-05%	18-08%	31-12%	49-04%	86-15%	1222-07%
Approved Violations	234-91%	1630-92%	1167-97%	333-90%	635-89%	347-84%	894-90%	908-85%	342-89%	2871-95%	553-91%	1261-95%	922-85%	198-92%	219-88%	1222-96%	482-85%	15394-93%
Total Notices Printed	234-91%	1630-92%	1167-97%	333-90%	635-89%	347-84%	894-90%	908-85%	342-89%	2871-95%	553-91%	1261-95%	922-85%	198-92%	219-88%	1222-96%	482-85%	15394-93%