

Customer Management Report (Culver City) All Detection Types

01-Oct-2019 to 31-Oct-2019

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-NAWA-01	CC-NAWA-03	CC-OVWA-01	CC-OVWA-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SEWA-01	CC-SEWA-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	TOTAL	
Total Processed Incidents	407	438	146	261	240	168	0	562	433	971	402	1361	325	191	232	836	340	176	276	205	7970	
Less Uncontrollable Factors																						
Obstruction	Plate Obstruction	0	0	0	0	0	1	0	0	1	1	0	0	0	0	0	0	0	0	0	3	
Police Rejects	Bicyclist	2	0	12	54	7	6	0	0	0	13	13	20	2	3	0	11	0	0	13	9	165
	Driver ID - Motorcyclist Helmet	4	3	2	1	3	0	0	0	0	8	4	16	0	1	0	3	3	3	0	1	52
	Driver ID - Poor Driver Image -	10	11	1	3	32	4	0	18	7	27	2	16	22	0	3	24	13	2	7	6	208
	Driver ID - Poor Driver Image -	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
	Driver Obstruction (PD)	5	9	1	0	3	1	0	1	3	34	11	12	3	1	1	5	6	0	1	1	98
	Driver Obstruction - Duckers	0	1	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1	0	0	0	3
	Emergency Vehicle	2	1	0	0	0	0	0	2	0	2	3	0	2	2	0	0	1	1	1	1	17
	Emergency Vehicle Responding	33	55	5	19	7	4	0	0	8	4	13	11	14	21	9	18	62	65	10	7	365
	Extended Vehicle	0	0	0	0	0	0	0	0	0	1	0	3	0	0	0	0	0	0	0	0	4
	Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	17	0	0	0	17
	Gender Mismatch	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1
	Limit Line Not Visible	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
	Multiple vehicles in frame	3	3	4	1	7	8	0	0	1	0	5	1	1	0	1	1	1	1	1	1	41
	No CDL and/or Date of Birth	7	4	3	7	6	4	0	1	4	11	13	40	7	4	0	6	5	4	9	6	141
	No Offence - Screeching Stop	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	1	0	0	0	2
	No Offence - Straight on Left	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	0	0	0	0	2
	No Offence- After Stop Bar	133	50	0	8	20	3	0	394	233	349	0	80	9	9	66	481	22	1	5	0	1863
	No Offence- False Trigger	1	7	1	2	6	7	0	1	4	7	3	0	0	0	0	1	1	2	0	1	44
	No Offence- Other	9	6	4	17	9	3	0	7	5	16	11	54	7	4	4	11	9	1	6	2	185
	No Plates	2	4	1	2	0	0	0	2	1	4	2	6	0	0	1	0	1	2	0	1	29
	Non Violation -Vehicle Behind	0	1	0	0	1	0	0	0	1	0	0	0	0	0	0	1	0	0	0	0	4
Non-violation - Late Stop	4	2	0	0	2	1	0	3	1	17	0	1	0	1	0	3	0	0	0	1	36	
On or Passed the Stop Bar (PD).	2	8	1	5	7	5	0	3	8	17	17	15	7	7	2	7	3	0	5	6	125	
Out of Country Plate	1	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	2	
Paper Plates	8	8	2	6	3	5	0	2	4	10	12	37	13	5	4	17	3	8	4	2	153	
Plate Obstruction (PD)	0	2	0	0	0	1	0	0	0	3	1	0	1	1	1	0	1	2	0	0	13	
Plate Unidentifiable	1	2	2	0	1	0	0	2	4	2	2	4	1	1	2	2	1	0	0	0	27	
Police Discretion	0	0	0	0	1	0	0	0	0	97	0	1	0	0	0	1	1	4	0	0	105	
Safe Turn On Red	0	1	0	0	0	0	0	0	1	0	0	7	0	1	0	1	1	0	0	0	12	
Straight Thru On Left	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	
Sun Glare	8	22	0	1	27	11	0	22	5	34	7	11	19	1	3	28	19	2	4	7	231	
Too Old	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1	
Vehicle Obstruction	3	8	1	1	3	9	0	1	4	5	8	32	10	8	6	33	5	2	12	4	155	
Total	238	208	40	127	145	73	0	461	295	664	128	369	118	71	103	656	177	100	78	56	4107	
Sub Total Violations	169	230	106	134	95	95	0	101	138	307	274	992	207	120	129	180	163	76	198	149	3863	

Generated By: WBROWNE

Generated On: 1/16/2020 10:17:44 AM

Customer Management Report (Culver City) All Detection Types

01-Oct-2019 to 31-Oct-2019

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-NAWA-01	CC-NAWA-03	CC-OVWA-01	CC-OVWA-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SEWA-01	CC-SEWA-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	TOTAL	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	169	230	106	134	95	95	0	101	138	307	274	992	207	120	129	180	163	76	198	149	3863	
Less Rejects																						
Police Rejects	Driver Unidentifiable images poor	1-01%	1-00%	0-00%	0-00%	7-07%	0-00%	0-00%	7-07%	1-01%	2-01%	3-01%	2-00%	0-00%	1-01%	5-04%	1-01%	6-04%	1-01%	4-02%	2-01%	44-01%
	Face Not in Frame	0-00%	1-00%	2-02%	0-00%	3-03%	3-03%	0-00%	1-01%	0-00%	17-06%	5-02%	3-00%	9-04%	2-02%	4-03%	3-02%	0-00%	4-05%	0-00%	9-06%	66-02%
	Face camera focus blurry	0-00%	1-00%	0-00%	0-00%	1-01%	1-01%	0-00%	2-02%	1-01%	1-00%	0-00%	3-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	11-00%	
	Face camera no flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-02%	0-00%	4-00%
	Misc Camera Issue	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	3-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	8-00%	
	Missing Image(s)	0-00%	0-00%	0-00%	0-00%	0-00%	3-03%	0-00%	0-00%	0-00%	1-00%	3-01%	0-00%	2-01%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	10-00%	
	No Images	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%	1-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	0-00%	7-00%	
	Plate Not in Frame	0-00%	1-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	6-00%	
	Plate Unclear	1-01%	4-02%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	3-00%	1-00%	0-00%	1-01%	0-00%	2-01%	0-00%	1-01%	16-00%	
	Scene Image Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Scene image no flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Vehicle not in frame	0-00%	1-00%	1-01%	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	4-01%	4-01%	0-00%	1-00%	1-01%	1-01%	0-00%	0-00%	0-00%	2-01%	3-02%	20-01%
Total		3-02%	9-04%	5-05%	1-01%	12-13%	10-11%	0-00%	10-10%	2-01%	30-10%	15-05%	18-02%	16-08%	4-03%	12-09%	6-03%	9-06%	5-07%	13-07%	15-10%	195-05%
Approved Violations		166-98%	221-96%	101-95%	133-99%	83-87%	85-89%	0-00%	91-90%	136-99%	277-90%	259-95%	974-98%	191-92%	116-97%	117-91%	174-97%	154-94%	71-93%	185-93%	134-90%	3668-95%
Total Notices Printed		166-98%	221-96%	101-95%	133-99%	83-87%	85-89%	0-00%	91-90%	136-99%	277-90%	259-95%	974-98%	191-92%	116-97%	117-91%	174-97%	154-94%	71-93%	185-93%	134-90%	3668-95%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Customer Management Report (Culver City) All Detection Types

01-Nov-2019 to 30-Nov-2019

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEDV-03	CC-NAWA-01	CC-NAWA-03	CC-OVWA-01	CC-OVWA-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SEWA-01	CC-SEWA-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	TOTAL	
Total Processed Incidents	214	309	147	169	132	130	0	339	359	616	345	1469	360	166	237	830	338	148	241	178	6727	
Less Uncontrollable Factors																						
Obstruction	Plate Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1	
Police Rejects	Bicyclist	3	0	6	29	11	3	0	0	13	17	17	1	4	1	8	2	0	5	7	127	
	Driver ID - Motorcyclist Helmet	1	1	1	1	2	0	0	1	0	5	0	10	3	0	2	2	3	1	1	34	
	Driver ID - Poor Driver Image -	9	12	2	1	16	4	0	22	2	14	6	8	30	3	3	31	13	2	4	185	
	Driver ID - Poor Driver Image -	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1	
	Driver Obstruction (PD)	0	4	2	0	2	1	0	1	2	22	4	7	4	1	2	5	0	1	3	3	64
	Driver Obstruction - Duckers	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
	Emergency Vehicle	0	0	0	0	0	0	0	0	0	0	2	1	1	1	1	3	1	0	0	0	10
	Emergency Vehicle Responding	15	48	6	13	0	9	0	3	1	7	6	11	22	24	11	15	58	53	5	8	315
	Extended Vehicle	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3	0	0	3
	Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	20	0	0	0	20
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	2	0	0	1	0	1	0	0	1	0	0	1	0	6
	Limit Line Not Visible	0	0	0	0	0	2	0	0	0	1	1	0	0	1	0	0	1	0	0	1	7
	Multiple vehicles in frame	0	3	2	1	1	2	0	1	2	1	1	0	1	0	0	0	2	1	2	0	20
	No CDL and/or Date of Birth	5	3	1	6	3	3	0	4	3	2	8	31	11	3	5	7	6	2	8	1	112
	No Offence - Straight on Left	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
	No Offence- After Stop Bar	55	33	1	9	11	1	0	187	228	257	2	87	20	12	77	508	19	0	15	2	1524
	No Offence- False Trigger	5	3	1	1	5	3	0	0	6	8	10	0	0	1	1	1	3	2	2	1	53
	No Offence- Other	3	6	2	4	3	2	0	5	6	33	4	41	14	1	5	9	5	0	6	2	151
	No Offence- Turn Trigger	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
	No Plates	1	1	0	1	1	0	0	0	0	2	3	2	0	0	2	3	0	0	2	0	18
	Non Violation -Vehicle Behind	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	1
	Non-violation - Late Stop	1	3	0	1	3	0	0	11	2	10	0	3	0	0	3	7	2	0	0	0	46
On or Passed the Stop Bar (PD)	1	7	1	3	4	10	0	4	8	7	18	17	4	4	6	2	6	0	3	6	111	
Out of Country Plate	0	1	0	0	0	0	0	2	0	0	0	0	1	0	0	0	0	0	0	0	4	
Paper Plates	4	7	3	4	2	0	0	4	8	6	9	37	7	4	4	6	4	1	2	3	115	
Plate Obstruction (PD)	1	0	1	1	0	2	0	0	0	1	0	1	1	0	0	0	0	1	0	1	10	
Plate Unidentifiable	1	0	2	0	0	4	0	1	0	2	3	8	1	1	1	0	2	1	0	2	29	
Police Discretion	0	1	1	0	0	0	0	0	0	24	0	4	4	0	0	0	2	0	0	0	36	
Safe Turn On Red	0	1	0	1	1	0	0	0	2	1	0	40	4	0	3	0	0	0	0	0	53	
Signal Obstruction	0	0	0	0	0	0	0	0	0	19	0	0	0	0	0	0	0	0	0	0	19	
Straight Thru On Left	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1	
Sun Glare	6	8	0	1	10	6	0	14	2	10	4	10	12	2	6	16	4	1	4	5	121	
Vehicle Obstruction	1	6	3	1	0	5	0	0	0	4	11	26	9	4	4	39	4	1	5	2	125	
Weather Conditions	0	0	1	0	0	0	0	0	0	0	1	1	0	0	2	1	0	0	0	0	6	
Total	112	148	36	79	75	57	0	263	272	451	111	363	151	66	137	666	156	72	68	48	3331	

Generated By: WBROWNE
Generated On: 1/16/2020 10:22:25 AM

Customer Management Report (Culver City) All Detection Types

01-Nov-2019 to 30-Nov-2019

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-NAWA-01	CC-NAWA-03	CC-OVWA-01	CC-OVWA-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SEWA-01	CC-SEWA-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	TOTAL	
Sub Total Violations	102	161	111	90	57	73	0	76	87	165	234	1106	209	100	100	164	182	76	173	130	3396	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	102	161	111	90	57	73	0	76	87	165	234	1106	209	100	100	164	182	76	173	130	3396	
Less Rejects																						
Police Rejects	Driver Unidentifiable images poor	1-01%	3-02%	1-01%	0-00%	2-04%	0-00%	0-00%	1-01%	2-02%	3-02%	0-00%	1-00%	2-01%	0-00%	4-04%	5-03%	0-00%	0-00%	1-01%	1-01%	27-01%
	Equipment Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-00%
	Face Not in Frame	0-00%	2-01%	1-01%	0-00%	0-00%	4-05%	0-00%	0-00%	2-02%	13-08%	3-01%	5-00%	1-00%	0-00%	2-02%	4-02%	4-02%	3-04%	2-01%	5-04%	51-02%
	Face camera focus blurry	0-00%	1-01%	0-00%	0-00%	3-05%	0-00%	0-00%	5-07%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	13-00%
	Misc Camera Issue	0-00%	0-00%	1-01%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Missing Image(s)	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-03%	0-00%	8-05%	8-03%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	21-01%
	Missing Video	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	4-00%
	No Images	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-01%	4-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-00%
	Plate Not in Frame	0-00%	1-01%	1-01%	1-01%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	2-01%	3-04%	0-00%	0-00%	10-00%
	Plate Unclear	0-00%	2-01%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	8-00%
	Plate burn out	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Scene Image Blurry	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	2-03%	0-00%	3-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-00%
	Vehicle not in frame	0-00%	1-01%	1-01%	0-00%	0-00%	2-03%	0-00%	0-00%	0-00%	2-01%	1-00%	1-00%	1-00%	0-00%	0-00%	1-01%	1-01%	0-00%	4-03%	15-00%	
Total		3-03%	11-07%	6-05%	1-01%	8-14%	7-10%	0-00%	11-14%	5-06%	38-23%	13-06%	9-01%	4-02%	0-00%	6-06%	14-09%	8-04%	8-11%	4-02%	10-08%	166-05%
Approved Violations		99-97%	150-93%	105-95%	89-99%	49-86%	66-90%	0-00%	65-86%	82-94%	127-77%	221-94%	1097-99%	205-98%	100-100%	94-94%	150-91%	174-96%	68-89%	169-98%	120-92%	3230-95%
Total Notices Printed		99-97%	150-93%	105-95%	89-99%	49-86%	66-90%	0-00%	65-86%	82-94%	127-77%	221-94%	1097-99%	205-98%	100-100%	94-94%	150-91%	174-96%	68-89%	169-98%	120-92%	3230-95%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Customer Management Report (Culver City) All Detection Types

01-Dec-2019 to 31-Dec-2019

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-NAWA-01	CC-NAWA-03	CC-OVWA-01	CC-OVWA-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SEWA-01	CC-SEWA-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	TOTAL		
Total Processed Incidents	360	432	154	103	128	73	0	673	1013	1235	319	1574	386	201	205	365	221	174	178	180	7974		
Less Uncontrollable Factors																							
Obstruction	Plate Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1		
Police Rejects	Bicyclist	7	2	13	14	8	2	0	2	0	37	14	12	1	2	1	2	2	0	7	8	134	
	Citation Issued manually	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Driver ID - Motorcyclist Helmet	1	2	0	1	1	0	0	2	1	6	0	2	0	0	0	0	0	0	0	0	2	18
	Driver ID - Poor Driver Image -	5	9	0	1	6	2	0	35	5	15	4	8	18	1	2	2	4	2	1	0	120	
	Driver ID - Poor Driver Image -	0	0	0	0	0	0	0	0	0	2	0	1	0	0	0	0	0	0	0	0	3	
	Driver Obstruction (PD)	1	2	1	0	2	0	0	0	9	28	7	4	6	2	0	3	1	2	2	2	72	
	Driver Obstruction - Duckers	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	Emergency Vehicle	0	0	1	0	0	0	0	1	0	1	0	1	1	0	0	0	0	0	0	0	5	
	Emergency Vehicle Responding	9	69	6	7	9	6	0	9	6	16	12	16	15	30	13	11	39	81	7	3	364	
	Extended Vehicle	0	1	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	2	
	Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	0	16	0	0	0	0	7	0	0	0	23	
	Incorrect/Incomplete DMV	0	0	0	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	2	
	Limit Line Not Visible	0	0	0	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	2	
	Multiple vehicles in frame	0	3	3	0	5	2	0	0	14	11	3	0	2	0	1	2	2	0	0	2	50	
	No CDL and/or Date of Birth	3	6	1	3	1	1	0	4	15	9	9	23	7	0	3	6	6	1	4	3	105	
	No Offence- After Stop Bar	241	113	12	15	8	2	0	372	712	376	0	107	14	10	89	188	27	1	10	4	2301	
	No Offence- False Trigger	3	3	0	0	8	0	0	1	3	16	2	0	2	0	0	1	1	0	1	1	42	
	No Offence- Other	5	3	1	0	5	2	0	3	9	15	1	59	10	6	1	1	1	0	7	3	132	
	No Offence- Turn Trigger	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	
	No Plates	0	3	0	0	1	0	0	1	2	2	0	7	4	0	3	0	0	2	0	1	26	
	Non Violation -Vehicle Behind	0	2	2	0	1	0	0	1	0	1	0	0	0	0	1	0	0	0	0	0	8	
	Non-violation - Late Stop	5	7	4	1	1	0	0	7	5	5	0	3	0	0	1	2	1	0	0	0	42	
On or Passed the Stop Bar (PD)	4	6	1	1	6	4	0	6	9	10	6	13	7	5	1	3	3	1	5	6	97		
Out of Country Plate	0	0	0	0	0	0	0	0	0	0	2	2	0	0	0	0	0	0	0	0	4		
Paper Plates	5	11	4	4	2	2	0	13	11	6	6	58	8	3	1	5	4	3	1	3	150		
Plate Obstruction (PD)	2	1	0	0	0	0	0	0	0	0	2	1	0	1	1	0	0	1	1	0	10		
Plate Unidentifiable	0	1	1	1	0	0	0	0	1	4	2	16	2	0	3	3	0	0	3	1	38		
Police Discretion	0	2	1	0	1	1	0	0	0	1	3	2	4	1	0	0	0	0	0	0	16		
Safe Turn On Red	0	0	0	0	0	0	0	0	3	0	0	20	3	0	0	1	0	0	0	1	28		
Signal Obstruction	2	1	0	0	0	0	0	2	0	383	0	0	0	0	0	3	0	0	0	0	391		
Straight Thru On Left	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	2		
Sun Glare	7	16	0	0	13	2	0	34	2	22	1	8	21	4	1	4	5	2	3	0	145		
Vehicle Obstruction	1	1	2	0	0	2	0	6	3	9	5	22	6	7	5	27	4	7	3	7	117		
Weather Conditions	1	0	1	0	3	0	0	1	0	1	1	1	0	0	3	1	0	0	0	1	14		
Wrong Plate	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	1		

Generated By: WBROWNE

Generated On: 1/16/2020 10:23:35 AM

Customer Management Report (Culver City) All Detection Types

01-Dec-2019 to 31-Dec-2019

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEDV-03	CC-NAWA-01	CC-NAWA-03	CC-OVWA-01	CC-OVWA-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SEWA-01	CC-SEWA-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	TOTAL	
Total	303	264	55	48	83	28	0	500	810	979	80	405	132	72	130	265	108	103	55	48	4468	
Sub Total Violations	57	168	99	55	45	45	0	173	203	256	239	1169	254	129	75	100	113	71	123	132	3506	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	57	168	99	55	45	45	0	173	203	256	239	1169	254	129	75	100	113	71	123	132	3506	
Less Rejects																						
Police Rejects	Driver Unidentifiable images poor	0-00%	3-02%	1-01%	1-02%	1-02%	0-00%	0-00%	18-10%	1-00%	2-01%	4-02%	4-00%	4-02%	0-00%	1-01%	3-03%	1-01%	5-07%	0-00%	0-00%	49-01%
	Face Not in Frame	0-00%	2-01%	1-01%	0-00%	2-04%	5-11%	0-00%	0-00%	4-02%	30-12%	5-02%	10-01%	5-02%	2-02%	2-03%	3-03%	0-00%	4-06%	0-00%	0-00%	75-02%
	Missing Image(s)	2-04%	1-01%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	4-02%	18-07%	4-02%	1-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	32-01%
	Missing Video	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	2-00%
	Plate Not in Frame	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	2-01%	0-00%	1-00%	0-00%	2-03%	1-01%	0-00%	0-00%	0-00%	1-01%	9-00%
	Plate Unclear	0-00%	1-01%	1-01%	1-02%	0-00%	1-02%	0-00%	0-00%	0-00%	3-01%	1-00%	1-00%	0-00%	3-02%	1-01%	0-00%	1-01%	0-00%	0-00%	0-00%	14-00%
	Plate burn out	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
	Scene Image Blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	1-01%	0-00%	0-00%	3-00%
	Scene image flash inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	1-00%
	Vehicle not in frame	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	6-02%	0-00%	2-00%	3-01%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	14-00%
Total		2-04%	9-05%	5-05%	2-04%	3-07%	7-16%	0-00%	18-10%	10-05%	62-24%	16-07%	18-02%	14-06%	5-04%	6-08%	10-10%	3-03%	11-15%	0-00%	1-01%	202-06%
Approved Violations		55-96%	159-95%	94-95%	53-96%	42-93%	38-84%	0-00%	155-90%	193-95%	194-76%	223-93%	1151-98%	240-94%	124-96%	69-92%	90-90%	110-97%	60-85%	123-100%	131-99%	3304-94%
Total Notices Printed		55-96%	159-95%	94-95%	53-96%	42-93%	38-84%	0-00%	155-90%	193-95%	194-76%	223-93%	1151-98%	240-94%	124-96%	69-92%	90-90%	110-97%	60-85%	123-100%	131-99%	3304-94%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Customer Management Report (Culver City) All Detection Types

01-Jan-2019 to 30-Dec-2019

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-NAWA-01	CC-NAWA-03	CC-OVWA-01	CC-OVWA-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SEWA-01	CC-SEWA-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	TOTAL
Total Processed Incidents	4408	4830	1833	2902	2158	1678	849	10296	5505	2785	4029	19120	4192	2199	2630	7987	3353	1538	2487	2224	87003
Less Uncontrollable Factors																					
Obstruction																					
Plate Obstruction	2	2	1	1	0	1	1	0	1	1	2	2	1	0	1	1	2	0	0	0	19
Police Rejects																					
Age Mismatch	0	0	0	0	0	0	0	0	0	0	0	3	1	0	0	1	0	0	0	1	6
Bicyclist	36	15	79	475	149	33	0	7	1	63	192	202	15	26	8	93	10	1	102	139	1646
Citation Issued manually	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Driver ID - Motorcyclist Helmet	13	28	13	21	13	4	1	6	1	19	13	88	19	10	3	45	23	19	5	15	359
Driver ID - Poor Driver Image -	152	158	33	54	224	60	27	336	74	56	56	102	272	40	60	192	167	41	62	80	2246
Driver ID - Poor Driver Image -	0	0	0	0	0	0	0	5	0	2	1	4	1	1	0	0	1	1	0	0	16
Driver Obstruction (PD)	23	57	14	17	22	4	5	62	58	83	98	105	35	23	28	51	16	15	19	25	760
Driver Obstruction - Duckers	0	1	1	0	0	0	0	0	0	1	0	0	0	1	0	0	1	0	1	0	6
Duplicate nomination	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Emergency Vehicle	7	4	4	1	4	4	2	14	5	3	10	20	6	7	7	16	9	4	3	2	132
Emergency Vehicle Responding	342	611	91	209	58	82	7	54	87	26	153	153	150	242	132	154	573	588	129	78	3919
Extended Vehicle	2	4	0	1	1	0	2	3	1	1	6	15	2	0	0	0	0	3	0	1	42
Funeral Procession/Police	0	0	0	0	0	0	0	0	0	0	0	16	0	0	0	0	44	0	0	0	60
Gender Mismatch	1	0	0	0	0	0	0	1	0	0	0	3	0	0	0	0	1	0	0	0	6
Incorrect/Incomplete DMV	2	2	1	2	0	0	0	2	1	0	1	8	5	1	0	3	0	0	2	0	30
Limit Line Not Visible	1	4	0	1	0	10	13	3	4	2	7	9	3	5	5	0	4	1	3	6	81
Multiple vehicles in frame	25	44	16	8	31	28	0	12	38	12	32	8	31	10	5	8	25	17	16	11	377
No CDL and/or Date of Birth	87	86	27	63	39	37	13	88	54	22	79	464	100	37	38	66	70	19	45	41	1475
No Offence - Screeching Stop	0	1	0	0	0	0	0	0	1	0	0	0	0	0	0	2	1	0	0	0	5
No Offence - Straight on Left	1	0	0	0	0	0	1	3	0	0	0	0	0	0	0	2	0	0	0	0	7
No Offence- After Stop Bar	1222	588	28	170	163	30	240	6128	3058	960	15	1135	169	104	840	4445	249	14	149	20	19727
No Offence- False Trigger	39	51	14	13	43	54	6	9	50	30	50	16	31	11	3	16	21	10	23	13	503
No Offence- Other	133	126	71	162	102	46	142	202	97	64	130	1026	251	72	51	107	88	32	64	46	3012
No Offence- Turn Trigger	0	0	0	2	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3
No Plates	10	28	17	8	5	7	5	37	17	8	22	93	15	8	27	24	15	11	12	18	387
Non Violation -Vehicle Behind	2	9	3	5	10	5	10	16	6	1	8	17	6	5	2	5	4	1	1	7	123
Non-violation - Late Stop	17	27	4	5	22	1	3	48	19	32	1	18	3	5	7	23	11	0	1	1	248
On or Passed the Stop Bar (PD).	44	89	12	44	86	43	27	281	111	34	67	157	58	35	43	111	50	3	41	37	1373
Out of Country Plate	2	2	1	1	0	0	0	4	1	0	4	9	3	1	0	1	1	0	0	1	31
Paper Plates	118	156	53	74	55	52	41	307	126	22	137	858	180	71	64	194	98	54	60	49	2769
Per E Tiedje	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	1
Plate Obstruction (PD)	9	18	4	6	3	6	3	5	2	4	8	16	6	4	2	4	5	11	4	5	125
Plate Unidentifiable	24	14	9	15	13	12	2	22	14	7	22	118	22	11	18	13	14	6	11	12	379
Police Discretion	8	5	2	5	3	1	2	13	7	122	4	55	11	3	4	15	5	4	0	0	269
Road Restrictions	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	1	0	0	2

Generated By: WBROWNE

Generated On: 1/16/2020 10:29:51 AM

Customer Management Report (Culver City) All Detection Types

01-Jan-2019 to 30-Dec-2019

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-NAWA-01	CC-NAWA-03	CC-OVWA-01	CC-OVWA-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SEWA-01	CC-SEWA-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	TOTAL	
Safe Turn On Red	0	2	0	1	1	0	0	0	6	1	0	67	7	1	3	2	1	0	0	1	93	
Signal Obstruction	2	1	0	0	0	0	0	2	0	402	0	0	0	0	0	4	0	0	0	0	411	
Straight Thru On Left	0	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0	0	4	
Sun Glare	163	215	20	38	243	105	40	413	88	66	61	94	270	30	43	201	174	37	80	107	2488	
Too Old	0	1	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	3	
Vehicle Obstruction	29	122	19	14	16	66	19	49	30	17	117	342	105	58	62	434	69	30	56	37	1691	
Weather Conditions	1	0	2	1	3	0	0	1	0	1	2	3	0	1	6	2	0	0	0	1	24	
Wrong or No DMV	0	0	1	0	2	0	1	0	0	0	0	1	0	0	1	0	0	0	0	0	6	
Total	2519	2471	540	1417	1312	691	613	8135	3958	2066	1299	5227	1778	823	1463	6235	1752	924	889	754	44866	
Sub Total Violations	1889	2359	1293	1485	846	987	236	2161	1547	719	2730	13893	2414	1376	1167	1752	1601	614	1598	1470	42137	
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
Available For Prosecution	1889	2359	1293	1485	846	987	236	2161	1547	719	2730	13893	2414	1376	1167	1752	1601	614	1598	1470	42137	
Less Rejects																						
Police Rejects	Digital Distortion	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	
	Driver Unidentifiable images poor	13-01%	27-01%	8-01%	2-00%	36-04%	9-01%	3-01%	50-02%	25-02%	7-01%	13-00%	33-00%	29-01%	10-01%	30-03%	33-02%	21-01%	20-03%	8-01%	12-01%	389-01%
	Equipment Malfunction	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%	0-00%	0-00%	3-00%	
	Face Not in Frame	7-00%	65-03%	21-02%	8-01%	32-04%	56-06%	12-05%	86-04%	41-03%	60-08%	73-03%	97-01%	77-03%	35-03%	31-03%	40-02%	34-02%	32-05%	8-01%	79-05%	894-02%
	Face camera flash inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%	0-00%	0-00%	3-00%	
	Face camera focus blurry	1-00%	8-00%	1-00%	4-00%	17-02%	4-00%	5-02%	28-01%	5-00%	2-00%	5-00%	9-00%	5-00%	4-00%	3-00%	5-00%	1-00%	1-00%	2-00%	2-00%	112-00%
	Face camera no flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	5-01%	4-00%	1-00%	11-00%	
	Insufficient Strobe Lighting	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	
	Misc Camera Issue	2-00%	5-00%	2-00%	1-00%	4-00%	9-01%	2-01%	0-00%	3-00%	2-00%	10-00%	24-00%	8-00%	2-00%	1-00%	1-00%	2-00%	0-00%	5-00%	2-00%	85-00%
	Missing Image(s)	6-00%	3-00%	0-00%	1-00%	2-00%	18-02%	0-00%	5-00%	3-00%	26-04%	36-01%	12-00%	2-00%	1-00%	3-00%	4-00%	4-00%	0-00%	0-00%	1-00%	127-00%
	Missing Video	2-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%	0-00%	1-00%	0-00%	1-00%	2-00%	1-00%	1-00%	1-00%	0-00%	0-00%	6-00%	0-00%	18-00%
	No Flash	0-00%	1-00%	0-00%	0-00%	0-00%	1-00%	2-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-00%	
	No Images	1-00%	9-00%	2-00%	1-00%	1-00%	14-01%	2-01%	5-00%	3-00%	4-01%	16-01%	13-00%	9-00%	1-00%	1-00%	4-00%	9-01%	0-00%	3-00%	2-00%	100-00%
	No Video	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	5-00%	0-00%	0-00%	2-00%	0-00%	1-00%	0-00%	1-00%	0-00%	10-00%
	Plate Not in Frame	2-00%	8-00%	3-00%	2-00%	4-00%	2-00%	0-00%	2-00%	1-00%	2-00%	9-00%	4-00%	4-00%	1-00%	3-00%	4-00%	6-00%	6-01%	7-00%	2-00%	72-00%
	Plate Unclear	9-00%	22-01%	8-01%	9-01%	9-01%	2-00%	1-00%	5-00%	3-00%	6-01%	11-00%	20-00%	7-00%	4-00%	6-01%	3-00%	7-00%	10-02%	9-01%	8-01%	159-00%
	Plate burn out	2-00%	3-00%	1-00%	0-00%	0-00%	0-00%	0-00%	2-00%	1-00%	3-00%	1-00%	0-00%	0-00%	0-00%	3-00%	1-00%	0-00%	1-00%	0-00%	0-00%	18-00%
	Rear Plate- no flash	0-00%	2-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Rear plate camera blurry	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Scene Image Blurry	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	2-00%	1-00%	4-01%	0-00%	0-00%	0-00%	0-00%	1-00%	1-00%	1-00%	0-00%	0-00%	0-00%	11-00%
	Scene image flash inappropriate	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	1-00%
	Scene image no flash	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
	Unclear Scene Image	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	1-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
	Vehicle not in frame	2-00%	3-00%	4-00%	2-00%	0-00%	3-00%	0-00%	3-00%	0-00%	11-02%	11-00%	3-00%	9-00%	1-00%	3-00%	2-00%	2-00%	4-01%	3-00%	10-01%	76-00%
Total		47-02%	158-07%	50-04%	31-02%	106-13%	120-12%	27-11%	191-09%	88-06%	128-18%	186-07%	222-02%	152-06%	61-04%	88-08%	100-06%	90-06%	82-13%	56-04%	119-08%	2102-05%

Generated By: WBROWNE
Generated On: 1/16/2020 10:29:51 AM

Customer Management Report (Culver City) All Detection Types

01-Jan-2019 to 30-Dec-2019

Operator Id: %

	CC-CEWA-01	CC-CIWA-01	CC-JECO-01	CC-JEDU-01	CC-JEDU-03	CC-JEOV-03	CC-NAWA-01	CC-NAWA-03	CC-OVWA-01	CC-OVWA-03	CC-SEGV-01	CC-SEGV-03	CC-SESL-01	CC-SESL-03	CC-SEWA-01	CC-SEWA-03	CC-SLBU-01	CC-SLBU-03	CC-WABE-01	CC-WABE-03	TOTAL
Approved Violations	1842-98%	2201-93%	1243-96%	1454-98%	740-87%	867-88%	209-89%	1970-91%	1459-94%	591-82%	2544-93%	13671-98%	2262-94%	1315-96%	1079-92%	1652-94%	1511-94%	532-87%	1542-96%	1351-92%	40035-95%
Total Notices Printed	1842-98%	2201-93%	1243-96%	1454-98%	740-87%	867-88%	209-89%	1969-91%	1459-94%	591-82%	2544-93%	13671-98%	2262-94%	1315-96%	1079-92%	1652-94%	1511-94%	532-87%	1542-96%	1351-92%	40034-95%

Legend: (P) = Production (I) = Inoperative

Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current