

Customer Management Report (Ventura) Redlight Incidents

01-Dec-2016 to 31-Dec-2016 Operator Id: %

Category	VE-8RJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMM-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents	22	241	12	38	156	61	37	99	65	7	44	46	43	28	48	44	177	59	1227
Less Uncontrollable Factors																			
Obstruction	2	24	2	1	1	8	1	3	0	0	1	2	6	4	4	0	2	1	62
Driver Obstruction/Duckers	0	0	0	0	0	0	0	0	1	0	2	0	0	0	0	0	0	0	3
Motor Cycle Helmet	0	1	0	1	3	5	1	1	0	0	0	3	0	0	0	0	0	0	3
Plate Obstruction	0	13	0	0	7	0	5	3	1	0	0	2	0	2	0	0	0	0	16
Vehicle Obstruction	0	1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Police Rejects	0	1	0	0	0	0	1	0	0	0	0	0	0	2	0	0	4	1	44
Multiple vehicles in frame	0	5	0	0	0	0	0	1	0	0	0	2	0	0	0	0	0	0	8
On or Passed the Stop Bar (PD)	2	11	1	11	11	5	0	4	2	0	10	3	4	1	1	8	13	5	92
Plate Unidentifiable	0	1	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Safe Turn On Red	0	19	0	0	0	0	0	11	3	0	0	0	0	0	0	0	0	0	37
Sun Glare	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Policy/Weath	0	1	0	0	1	2	0	1	0	0	0	0	0	2	0	0	1	0	8
Extended Vehicle	0	42	0	1	9	2	4	4	6	0	2	2	4	2	4	1	22	11	116
Sun Glare	0	1	0	0	3	1	0	1	2	0	0	0	2	1	0	1	8	1	21
Weather/Nature	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Registration	0	12	0	2	3	3	0	5	4	0	4	1	0	0	0	0	0	0	1
Out of Country Plate	1	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Paper Plates	1	0	0	2	3	3	0	2	3	0	1	1	0	0	0	0	0	0	4
Wrong or No DMV	6	3	0	2	3	0	0	2	3	1	1	1	0	0	0	0	1	1	46
Total	1	135	3	16	42	26	12	22	22	1	20	16	16	14	17	10	28	28	485
Sub Total Violations	16	106	9	20	114	35	25	62	43	6	24	30	27	14	31	34	115	31	742
Less in Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	16	106	9	20	114	35	25	62	43	6	24	30	27	14	31	34	115	31	742
Less Rejects																			
Camera	0-00%	0-00%	0-00%	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Face Camera Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Malfunction	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%

Generated By: TRAMPALL
Generated On: 3/16/2017 1:35:27 PM

Customer Management Report (Ventura) Redlight Incidents

01-Dec-2016 to 31-Dec-2016 Operator Id: %

Category	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MAT10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMC-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Face Camera No Flash	0-00%	0-00%	0-00%	0-00%	4-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Face Not in Frame	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-17%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Plate Burn Out	0-00%	1-01%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Rear Plate Flash Inappropriate	0-00%	0-00%	0-00%	1-05%	0-00%	2-08%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	3-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%
Police	0-00%	11-10%	0-00%	0-00%	1-01%	0-00%	0-00%	1-02%	1-02%	0-00%	0-00%	0-00%	0-00%	1-07%	0-00%	0-00%	0-00%	1-01%	16-02%
Police Rejects	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-04%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Under Scene Image	0-00%	12-11%	0-00%	1-05%	7-05%	2-06%	2-08%	2-03%	1-02%	1-17%	0-00%	1-03%	0-00%	1-07%	0-00%	1-03%	0-00%	2-02%	33-04%
Total	16-100%	94-89%	9-100%	19-95%	107-94%	33-94%	23-92%	60-97%	42-98%	5-83%	24-100%	29-97%	27-100%	13-83%	31-100%	33-97%	113-98%	31-100%	709-96%

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach:" drop down list, the statuses reflected in this report will only indicate the current

Customer Management Report (Ventura) Redlight Incidents

01-Jan-2017 to 31-Jan-2017 Operator id: %

Total Processed Incidents	VE-BRJ0-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
20	239	9	34	139	39	29	59	80	11	33	55	33	24	92	60	131	39	1126	
Less Uncontrollable Factors																			
Obstruction	2	16	3	1	1	1	1	2	0	0	2	0	0	0	2	0	0	2	53
Obstruction	0	1	0	0	0	2	0	0	2	0	0	0	0	1	0	0	0	0	8
Motor Cycle Helmet	0	1	0	2	2	1	1	0	0	0	0	2	0	0	0	0	0	0	9
Plate Obstruction	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	1
Signal Obstruction	1	10	0	0	6	0	3	0	0	1	2	1	2	0	2	1	1	1	36
Vehicle Obstruction	0	0	0	0	0	0	1	0	0	0	0	0	0	1	0	0	0	1	3
Police Rejects	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	1
Driver Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Funeral Procession/Police	0	8	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	10
Multiple vehicles in frame	0	19	0	0	6	8	1	13	4	2	2	2	0	2	0	0	0	0	96
On or Passed the Stop Bar (PD)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	2
Plate Obstruction (PD)	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	1
Police Discretion	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Safe Turn On Red	0	18	0	0	0	0	0	6	0	0	0	0	0	0	0	0	0	0	28
Policy/Weather	0	2	0	0	1	0	0	0	0	0	1	0	0	0	0	0	0	0	5
Extended Vehicle	0	44	0	0	7	1	0	1	8	0	1	0	0	1	3	1	19	5	91
Sun Glare	0	6	0	3	5	2	1	1	5	1	1	3	2	2	4	2	4	4	42
Weather/Nature	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Registration	1	6	2	2	6	1	1	2	4	2	0	3	2	2	4	0	4	1	43
Out of Country Plate	1	5	0	2	3	0	1	3	2	0	0	1	1	1	3	1	2	1	27
Paper Plates	2	5	0	2	2	0	1	2	2	0	0	0	1	1	1	1	2	1	27
Wrong or No DMV	9	137	5	16	39	17	10	28	17	6	12	17	13	11	32	22	34	23	457
Sub Total Violations	11	102	4	18	100	22	19	31	54	5	21	38	20	13	60	38	97	16	669
Less In Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	11	102	4	18	100	22	19	31	54	5	21	38	20	13	60	38	97	16	669
Less Rejects																			

Generated By: TRANDALL
Generated On: 3/16/2017 1:30:41 PM

Customer Management Report (Ventura) Redlight Incidents

01-Jan-2017 to 31-Jan-2017 Operator Id: %

Camera Malfunction	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MAT0-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VINA-01	TOTAL
Face Camera Flash	0.00%	1.01%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	4.01%
Face Camera Focus Blurry	0.00%	0.00%	0.00%	0.00%	1.01%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.03%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	3.00%
Face Not in Frame	0.00%	0.00%	1.25%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.05%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	2.00%
Plate Burn Out	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.05%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
Rear Plate Camera Blurry	0.00%	0.00%	0.00%	0.00%	0.00%	1.01%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	3.00%
Rear Plate Flash Inappropriate	0.00%	0.00%	0.00%	0.00%	0.00%	4.18%	0.00%	0.00%	0.00%	1.20%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	5.01%
Scene Image No Flash	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.03%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
Police Rejects	0.00%	11.11%	0.00%	0.00%	0.00%	0.00%	0.00%	2.06%	3.06%	0.00%	0.00%	0.00%	0.00%	1.08%	0.00%	1.03%	1.01%	1.05%	20.03%
Red-light not visible in	0.00%	0.00%	0.00%	0.00%	1.01%	0.00%	0.00%	1.01%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
Unclear Scene Image	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.02%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	1.00%
Total	0.00%	12.12%	1.25%	0.00%	0.00%	0.00%	0.00%	3.10%	4.07%	1.20%	1.05%	0.00%	0.00%	1.08%	0.00%	1.03%	1.01%	1.05%	41.06%
Approved Violations	11-100%	90-88%	3.75%	18-100%	97.97%	17.77%	19-100%	28-80%	50.93%	4.80%	20.95%	37.97%	19.95%	12.92%	60-100%	36-95%	93.86%	14.88%	628.94%
Total Notices Printed	11-100%	90-88%	3.75%	18-100%	97.97%	17.77%	19-100%	28-80%	50.93%	4.80%	20.95%	37.97%	19.95%	12.92%	60-100%	36-95%	93.86%	14.88%	628.94%

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach" drop down list, the statuses reflected in this report will only indicate the current

Customer Management Report (Ventura) Redlight Incidents

01-Feb-2017 to 28-Feb-2017 Operator Id: %

Operator	VE-BRJ0-01	VE-CATH-01	VE-FOV-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAML-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VITP-01	VE-VITP-03	VE-VIVA-01	TOTAL
Total Processed Incidents	14	211	9	35	154	30	37	56	72	11	29	60	24	31	68	90	170	56	1157

Less Uncontrollable Factors

Obstruction	2	19	3	2	3	3	1	2	2	0	1	5	5	5	8	2	6	5	74
Driver Obstruction/Duckers	0	0	0	0	1	0	0	1	0	0	2	0	0	0	0	0	1	0	5
Motor Cycle Helmet	0	2	0	0	0	2	0	0	0	1	0	3	0	0	0	2	0	1	11
Plate Obstruction	0	7	0	1	9	1	4	1	0	0	0	4	0	1	4	1	5	1	39
Vehicle Obstruction	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Police	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1
Rejects	0	5	0	0	0	0	0	0	1	0	0	1	0	0	0	0	0	0	7
Multiple vehicles in frame	0	14	0	9	9	2	0	5	4	1	2	5	2	0	0	0	0	0	91
On or Passed the Stop Bar (PD)	0	0	0	0	0	0	1	1	1	0	0	0	0	0	0	0	0	0	3
Plate Obstruction (PD)	0	14	0	0	0	0	0	7	2	0	0	0	0	0	0	0	0	0	26
Safe Turn On Red	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Sun Glare	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Policy/Weath	0	1	0	0	1	0	0	0	0	0	0	3	0	0	0	0	0	0	7
Extended Vehicle	1	31	0	1	13	1	2	4	7	2	3	4	3	4	2	8	30	13	129
Sun Glare	0	4	0	3	1	0	0	0	0	0	0	2	2	0	0	0	0	0	28
Weather/Nature	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Registration	1	9	0	1	3	2	2	2	0	1	1	1	1	3	2	1	3	2	35
Out of Country Plate	0	2	0	2	4	0	0	4	6	0	2	1	0	1	1	0	0	0	29
Paper Plates	0	108	0	19	44	11	11	27	26	6	11	27	13	17	24	31	70	35	487
Whrong or No DMV	4	0	3	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	10	103	6	16	110	19	26	29	46	5	18	33	11	14	44	59	100	21	670
Sub Total Violations	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Less In Progress	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Available For Prosecution	10	103	6	16	110	19	26	29	46	5	18	33	11	14	44	59	100	21	670

Generated By: **TRANNDALL**
Generated On: 3/16/2017 1:33:16 PM

Customer Management Report (Ventura) Redlight Incidents

01-Feb-2017 to 28-Feb-2017 Operator Id: %

Category	VE-BRJO-01	VE-CATH-01	VE-FOVI-01	VE-JONB-01	VE-MA10-01	VE-MALE-01	VE-MAMI-01	VE-MIDE-01	VE-MITG-01	VE-TGDA-01	VE-THSE-01	VE-VIMO-01	VE-VIOP-01	VE-VIRA-01	VE-VITG-01	VE-VTP-01	VE-VTP-03	VE-VVA-01	TOTAL	
Rear Plate Camera Bury	0-00%	0-00%	0-00%	0-00%	0-00%	1-01%	0-00%	0-00%	0-00%	1-05%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Rear Plate No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Scene Image No Flash	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	2-00%
Police Reflects	0-00%	2-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-02%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	4-01%
Driver Unidentifiable images poor	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-20%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Redlight not visible in	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	1-00%
Unclear Scene Image	0-00%	4-04%	0-00%	0-00%	0-00%	0-00%	0-00%	1-03%	2-04%	3-50%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	0-00%	16-02%
Total	10-100%	99-96%	6-100%	16-100%	109-99%	17-99%	26-100%	28-97%	44-96%	2-40%	18-100%	33-100%	11-100%	14-100%	44-100%	59-100%	98-98%	20-95%	654-98%	
Approved Violations	10-100%	99-96%	6-100%	16-100%	109-99%	17-99%	26-100%	28-97%	44-96%	2-40%	18-100%	33-100%	11-100%	14-100%	44-100%	59-100%	98-98%	20-95%	654-98%	
Total Notices Printed	10-100%	99-96%	6-100%	16-100%	109-99%	17-99%	26-100%	28-97%	44-96%	2-40%	18-100%	33-100%	11-100%	14-100%	44-100%	59-100%	98-98%	20-95%	654-98%	

Legend: (P) = Production (I) = Inoperative
 Note: If you selected "All" from the "Approach" drop down list, the statuses reflected in this report will only indicate the current